

Job Information

Job #:	136440			Date:	June 1, 2018	
Priority:	-	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Chemours		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Siemens	Enclosure :	Open Drop Proof (ODP)	Enclosure Type image
Serial#:	1-5113-38799-1-1	Model#:	· · /	
Service Factor:		Frame:	507us	
Horsepower/kW:	250	Rated RPM:		
Rated Amps:		Rated Voltage:	460	
Phase:	3	Cycles:		
Special design:	No			



DE

ODE

F1

F2











WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.


Does the shaft turn freely?:	Yes	Contaminant(s):	Grease
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Full
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Loose	Bearings DE make:	NTN
Insulated:	No	Bearing DE Size:	315
Bearings ODE:	Worn	Bearings ODE make:	NTN
Bearing Type:	Ball	Bearing ODE Size:	315
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301





CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	Watery
Grease Amt ODE:	Full	Grease Cond. ODE:	Watery
Seals DE type:	Slinger	Seals Image:	
Seals DE size:			Not Available
Seals DE (inbound) condition :			
		Seals Image 2:	
Seals ODE type:	Slinger	ocais image 2.	Not
Seals ODE size:			Available
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301




Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:

Not Available



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)


Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	6	Terminal Markings:	Black yellow red	
Length of leads:	18	REF: NEMA Stds Markings Identifie	s. MG 1-2009, Rev. 1- ed By Color:	-2010, 2.41-Terminal
Size of leads:	Awg 1	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:	Regular	Connections As Rec	ceived:	
Lug Condition:	Good	т	erminal	Lugs
Lug size:				
Lug Attachment:	_	S.		



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Painted	Winding	g image	Winding Thermal	Protection:	Yes
Winding condition :	Solid				Ν	lot
Winding Thermal Protection DE:	_				Avai	lot ilable
Winding Thermal Protection ODE:	_					
Stator test results:	Rewind					
Megs incoming: Good	b	Surge incoming:	Good	Hi-pot inco	oming: G	àood
Winding Resistance In	coming					
Phase	es A to B	Phases B to C	Phases	C to A	Resistive im	balance
Incoming						
Leads/jumpe	ers: Ok		Lead jump	per Image. :		
If other, leads/jumpe	ers:				Nc Availa	ot able

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Over greased

Cause of Failure

D.e bearing over greased

Comments

Service Tech name: Terry f

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301