

## Job Information

Job #: 138121

Date: September 24, 2018

Priority: 3

Authorized OT: No

Authorized by: Terry Frazier

## Customer Information

Name: Ktg

Reason: Motor was rebuilt in 2011

Contact: Alex Kisel

Motor#:

PO#:

Application: —

Special notes: Check to see if bolts are loose on endbells

## Name Plate Information

Manufacturer: GE

Enclosure : Open Drop Proof (ODP)

Enclosure Type image

Serial#:

Model#: 5ks444ss208a

Service Factor:

Frame: 444t

Horsepower/kW: 125

Rated RPM: 1780

Rated Amps: 137

Rated Voltage: 460

Phase:

Cycles:

Special design: No



Nameplate

DE

ODE

F1

F2

Top



## Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No

Contaminant(s): Other

Shaft rotation: Bi-directional

Contaminant(s) Amt: Quart

Shaft grounding device present?: No

Contaminant Image:



Type of grounding device: N/A

Shaft runout(TIR-Inbound): .001

Bearings DE: Worn

Bearings DE make: SKF

Insulated: No

Bearing DE Size: 6318ZZ

Bearings ODE: Worn

Bearings ODE make: SKF

Bearing Type: Ball

Bearing ODE Size: 6318ZZ

Bearings Retainer: Yes

Thermal Protection: No

Retainer condition: Good

Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection

Not Available

## Mechanical Inspection (Continued)

Lubrication Type: Grease

Thermal Protection device DE: N/A

Lubrication brand inbound: Unknown

Thermal Protection device ODE: N/A

Lubrication brand outbound: Unknown

Grease Amt DE: Full

Grease Cond. DE: Other

Grease Amt ODE: Full

Grease Cond. ODE: Other

Seals DE type: Slinger

Seals Image:

Seals DE size:

Seals DE (inbound) condition : Worn



Seals Image 2:

Seals ODE type: N/A

Seals ODE size: N/A

Seals ODE (inbound) condition : N/A

Not  
Available

Shaft damage cause: None

Shaft Image:



## Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket: N/A

Fan: Ok

Frame cond.: Good

Not Available



Motor Mount Position: Horizontal/Foot mount

Endbell type: Single piece

Missing parts?

☒ J-Box cover ☐ O-rings ☒ J-Box☐ HH cover ☐ Glands ☐ None

Other missing parts

Endbell Image:





## Mechanical Inspection (Continued)

### Air Gap Measurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0

ODE @ 0

—

DE @ 90

ODE @ 90

DE @ 180

ODE @ 180

DE @ 270

ODE @ 270

## AC Electrical Inspection

Number of leads: 6

Terminal Markings: 1,2,3,7,8,9

Length of leads: 1.5'

REF: NEMA Std. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:

Size of leads:

1-Blue  
2-White  
3-Orange  
4-Yellow

5-Black  
6-No color assigned  
7-No color assigned  
8-Red

P1-No color assigned  
P2-Brown

Lead condition: Good

Lug type: Hole

Connections As Received:

Lug Condition: Good

Lug size:

Lug Attachment: Acceptable

Terminal



Lugs



## AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor

Rotor Condition: Melted bars

Num rotor bars:

Num broken bars:



### Rotor Test Results

Visual: Fail

Growler: Fail

Single phase: Fail

Stator type: Factory

If other, stator type:

Stator condition: Ground

If other, stator condition:

Failure location: In slot

If other, stator failure:

Stator Image:



Failure Image:



#### WEST TENNESSEE

7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

#### CENTRAL ARKANSAS

6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254

## AC Electrical Inspection (Continued)

Winding color: Still has color

Winding image

Winding Thermal Protection: No

Winding condition : Charred

Winding Thermal  
Protection DE: BadWinding Thermal  
Protection ODE: Bad

Stator test results: Rewind

Not  
Available

Megs incoming: Bad

Surge incoming: Bad

Hi-pot incoming: Bad

### Winding Resistance Incoming

Phases A to B

Phases B to C


Phases C to A

Resistive imbalance

Incoming

Leads/jumpers: Ok

Lead jumper Image. :



If other, leads/jumpers:

## Conclusion

### Component Failure

Primary: Rotor/Stator. Secondary: Emulsification of bearing lubricant.

### Cause of Failure

Rotor Failure due to unbalanced voltage that resulted in overload of rotor.

### Comments

Water was found within stator and bearing grease. Bearing contained a mixture of two different grease types contaminated with water and the lubricant was extremely milky and white from emulsification. Bearing lubricant failure was taking place when the primary cause of failure occurred. Stator winding was blown in the slots at the 2,3, & 5 o'clock positions from voltage imbalance, and the rotor was blown open as the result of voltage imbalance.

Service Tech name: TF

Service Tech signature:

A handwritten signature in black ink, appearing to read 'Terry', followed by a large, stylized flourish or checkmark.**WEST TENNESSEE**

7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

**CENTRAL ARKANSAS**

6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254