

Job Information

Job #:	139552				Date:	April 17, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Penn A Kem		Reason:	Motor inspection
Contact:	Patricia Lott	Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Тасо	Enclosure :	Open Drop Proof (ODP)	Enclosure Type image
Serial#:	Rdac184056-1	Model#:	Aehh-8n	
Service Factor:		Frame:	449TDZ	
Horsepower/kW:	350	Rated RPM:	1788	
Rated Amps:	387	Rated Voltage:	460	
Phase:	3	Cycles:		
Special design:	No			

Nameplate

DE

ODE

F1

F2





WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254









Тор



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	
Insulated:	No	Bearing DE Size:	6320
Bearings ODE:	Worn	Bearings ODE make:	NTN
Bearing Type:	Ball	Bearing ODE Size:	6316
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image





Bearing Make Image

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	1/4	Grease Cond. DE:	Other
Grease Amt ODE:	0	Grease Cond. ODE:	Other
Seals DE type:	Labyrinth	Seals Image:	
Seals DE size:			
Seals DE (inbound) condition :	Ok		
Seals ODE type:	Labyrinth	Seals Image 2:	
Seals ODE size:			
Seals ODE (inbound) condition :	Worn		
Shaft damage cause:	Other	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:	N/A	Fan:	Ok	Frame co	nd.: Good
Motor Mount Posi	tion: Horizontal/F	oot mount		Endbell type:	Single piece
Missing parts?	?			Endbell Image:	DEC
J-Box cover	O-rings	J-Box			
HH cover	Glands	V None			
Other missing pa	irts				A

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)


Air Gap Meaurements (N/A on Single P	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	6	Terminal Markings:				
Length of leads:	12 inches	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:				
Size of leads:	2 AWG	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown		
Lead condition:	Good	4-Yellow	8-Red			
Lug type:		Connections As Received:				
Lug Condition:	Good	ТТ	erminal	Lugs		
Lug size:	2awg			<u>en</u> ,		
Lug Attachment:	_					



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	g image	Winding Therma	al Protection:	No		
Winding condition :	Solid							
Winding Thermal Protection DE:	_							
Winding Thermal Protection ODE:	_							
Stator test results:	Rewind							
Megs incoming: Good Surge incoming: Bad Hi-pot incoming: Goo					ood			
Winding Resistance In	coming							
Phase	es A to B	Phases B to C	Phase	es C to A	Resistive imb	balance		
Incoming								
Leads/jumpe	ers: Ok		Lead jur	mper Image. :				
If other, leads/jumpe	ers:							

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Bearing on # 2 end

Cause of Failure

Lack of grease. No grease in bearing

Comments

Surge test after tear down came back as failed. Will wash and bake then retest.

Service Tech name: E

Dan Mahan

Service Tech signature:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301