

Job Information

Job #:	140003				Date:	June 24, 2019
Priority:	_	Authorized OT:	No	Authorized by:	Terry f	

Customer Information

Name:	Hi speed Ir	Reason:		
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Siemens	Enclosure :	Open Drop Proof (ODP)	Enclosure Type image
Serial#:		Model#:	(ODF)	
Service Factor:		Frame:	B449	
Horsepower/kW:	250	Rated RPM:	1185	
Rated Amps:	280	Rated Voltage:	460	
Phase:		Cycles:		
Special design:	No			



DE

ODE

F1

F2

Тор













WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Grease
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	2
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	SKF
Insulated:	No	Bearing DE Size:	318
Bearings ODE:	Worn	Bearings ODE make:	SKF
Bearing Type:	Ball	Bearing ODE Size:	316
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301





CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	N/A
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	N/A
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	N/A	Seals Image:	201
Seals DE size:			No-H nd
Seals DE (inbound) condition :			
Seals ODE type:	N/A	Seals Image 2:	
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	



t Available

+ Available

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:	Ok	Fan:	Ok	Frame cor	nd.: Good
	t Available ler nain-teamee				
Motor Mount Pos	ition: Horizontal/F	oot mount		Endbell type:	Single piece
Missing parts	?			Endbell Image:	
J-Box cover	O-rings	J-Box			
HH cover	Glands	None None			
Other missing pa	arts				

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	6	Terminal Markings:		
Length of leads:	18 inches	REF: NEMA Stds Markings Identifie	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:	AWG 1	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:	Regular	Connections As Red	ceived: 1-3	
Lug Condition:	Good	T	Ferminal	Lugs
Lug size:	5/16		The	
Lug Attachment:	_		D	

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding c	olor:	Like new	Windin	g image	Winding Therma	al Protection:	Yes
Winding condit	ion :	Solid	П.				
Winding The Protection		_					
Winding The Protection C		_					F
Stator test res	ults:	Rewind					
Megs incoming:	Bad		Surge incoming:	Bad	Hi-pot ir	ncoming: Ba	ad
Winding Resista	ance In	coming					
	Phas	es A to B	Phases B to C	Phase	es C to A	Resistive imb	alance
Incoming	0.01	6	0.016	0.016	3		
	s/jumpo			Lead jur	nper Image. :		
If other, lead	Sijumpe	515.					P

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Rewind stator

Cause of Failure

Short

Comments

Short in windings , d.e bearing bushing was to tight locked on bearing spun in end bell

Service Tech name: Terry f

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301