

Job Information

Job #:	142805				Date:	July 6, 2020
Priority:	_	Authorized OT:	No	Authorized by:	Terry f	

Customer Information

Name:	Nucor		Reason:	Eddy current
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Pnh	Enclosure :	Open Drop Proof (ODP)	Enclosure Type image
Serial#:	273037-892	Model#:		
Service Factor:		Frame:		
Horsepower/kW:		Rated RPM:	Na	S. I.
Rated Amps:	20	Rated Voltage:	Na	
Phase:		Cycles:		
Special design:	No			



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	_	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	SKF
Insulated:	No	Bearing DE Size:	215
Bearings ODE:	Worn	Bearings ODE make:	SKF
Bearing Type:	Ball	Bearing ODE Size:	2152rs
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301





CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	N/A
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	N/A
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	N/A	Seals Image:	
Seals DE size:			No-
Seals DE (inbound) condition :			
Seals ODE type:	N/A	Seals Image 2:	<u> </u>
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	en



t Available

Available

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:	Ok		Fan:	Ok	Frame co	nd.:	Good
	rt Arailable under nain-tennnee						
Motor Mount Pos	sition: Horizontal/F	oot mount			Endbell type:	Sing	le piece
Missing parts		J-Box			Endbell Image:		

Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	_	Terminal Markings:	1-4	
Length of leads:		REF: NEMA Stds Markings Identifie	. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	_	4-Yellow	8-Red	
Lug type:		Connections As Rec	eived:	
Lug Condition:	_	т	erminal	Lugs
Lug size:				
Lug Attachment:	_			

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type:	Cast Aluminum	-		Rotor
Rotor Condition:	Ok	Num rotor bars: um broken bars:		
Rotor Test Results				
Visual: Pass	Growler:	Pass	Single phase:	Pass
Stator type: Stator condition:	Factory Ok	If other, stator ty If other, stator conditi		
Failure location:	In slot	If other, stator failu	ıre:	
Stator Image:		Failure Ima	ge:	

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Painted	Winding	ı image	Winding Therma	Protection:	Yes
Winding condition :	Solid					
Winding Thermal Protection DE:	_		Geb			
Winding Thermal Protection ODE:	_	and the second se				
Stator test results:	Rewind					
Megs incoming: Good	d	Surge incoming:	Good	Hi-pot ind	coming: G	ood
Winding Resistance Inc	coming					
Phase	es A to B	Phases B to C	Phase	es C to A	Resistive imb	balance
Incoming						
Leads/jumpe	ers: Ok		Lead jun	nper Image. :		
If other, leads/jumpe	ers:				No+7 vider	Trailable nain-tenance

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Winding meg ohm reading were low

Cause of Failure

Brake had low meg ohm reading needed bake moisture inside winding

Comments

Cleaned and baked brake looks and test fine.

Service Tech name: Terry f

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301