

Job Information

Job #: 94009 Date: March 2, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: AR state military dept Reason:

Contact: Motor#: PO#:

Application: — Special notes:

Name Plate Information

Manufacturer: Sulzer Enclosure: Totally Enclosed Enclosure Type image Non-Ventilated

Serial#: 00461999/2017 Model#: ABSXFP15GE-

C014PE1.05

Service Factor: Frame:

Horsepower/kW: 14.1 Rated RPM: 1754

Rated Amps: 35.4/17.7 Rated Voltage: 230/460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:











Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: CCW Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size:

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size:

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image Bearing Make Image Bearing Retainer Image Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: —

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: N/A Grease Cond. DE: Other

Grease Amt ODE: 1/4 Grease Cond. ODE: Gritty

Seals DE type: Other Seals Image:

Seals DE size:

Seals DE (inbound) condition: Bad

Seals Image 2:

Seals ODE size:

Seals ODE type:

N/A

Seals ODE (inbound) condition

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)

Water jacket:

N/A



N/A

Frame cond.:

Good







Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 50'

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 10 awg P2-Brown

2-White 6-No color assigned

3-Orange 7-No color assigned

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type:

Lug Condition: Terminal Lugs

Lug size:

Lug Attachment:



Fax 901-873-5301

Failure Image:



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Stator Image:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok

If other, leads/jumpers:



Conclusion

Component Failure

Bearing spun inside Opposite drive end bearing housing fit

Cause of Failure

Seal failed as a result of excessive bearing play on o.d.e

Comments

Service Tech name: Terrence Holland

Service Tech signature: