

Job Information

Job #: 94127 Date: March 29, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Ryerson Reason:

Contact: Motor#: PO#:

Application: — Special notes: Fan blade and base attachments.

Name Plate Information

Manufacturer: Baldor Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled Serial#: Z1304260044 Model#: 09P0112601

Service Factor: 1.15 Frame: 256T

Horsepower/kW: 20 Rated RPM: 3520

Rated Amps: 46/23 Rated Voltage: 230/460

Phase: 3 Cycles: 60

·

No

Nameplate DE ODE F1 F2 Top



Special design:











Fax 901-873-5301

CENTRAL ARKANSAS



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: Koyo

Insulated: No Bearing DE Size: 63092Z

Bearings ODE: Worn Bearings ODE make: NACHI

Bearing Type: Ball Bearing ODE Size: 6208ZE C3

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: 1/2 Grease Cond. DE: Gritty

Grease Amt ODE: 1/2 Grease Cond. ODE: Gritty

Seals DE type: Slinger

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: Slinger

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Mechanical Inspection (Continued)

Brg. Image:



Water jacket: Ok Fan: Ok Frame cond.: Good



The second second

Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings:

Length of leads: 6" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —

Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image:





AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal

Protection ODE:

Stator test results: Rewind



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.462 0.467 0.465 0.6

Leads/jumpers: Ok

If other, leads/jumpers:



Conclusion

Component Failure

Bearings/o.d.e end-bell bearing housing fit had excessive wear.

Cause of Failure

Comments

Recommend repairing o.d.e, bearing housing fit. Also the bearing grease was contaminated with grit.

Service Tech name: Terrence Holland

Service Tech signature: