

Job Information

Job #:	94351				Date:	May 29, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	L'Oreal		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Totally Enclosed Fan Cooled
Serial#:	W1501282685	Model#:	35R755-0672G1
Service Factor:	1.00	Frame:	145TCZ
Horsepower/kW:	2	Rated RPM:	3450
Rated Amps:	5.4/2.7	Rated Voltage:	230/460
Phase:	3	Cycles:	60

Enclosure Type image



Nameplate

Special design:

DE

No

ODE

F1

F2

Тор









WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	No	Contaminant(s):	None
Shaft rotation:	CW	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			
Shaft runout(TIR-Inbound):			
Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image

Bearing Make Image

Bearing Retainer Image

Thermal Protection

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	Thermal Overloads
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type: Seals DE size:	Other	Seals Image:	0
Seals DE (inbound) condition :			
Seals ODE type: Seals ODE size: Seals ODE (inbound) condition :	N/A	Seals Image 2:	
Shaft damage cause:	Keyway bad	Shaft Image:	



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Water jacket: N/A

Fan:

N/A

Frame cond.:

Single piece

Motor Mount Position: Horizontal/Foot mount

Missing parts?

J-Box cover	O-rings	J-Box
HH cover	Glands	None

Other missing parts


Rear mounted Fan blade missing

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Endbell type:





MILLINGTON, TN LITTLE ROCK, AR



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	_	Terminal Markings:				
Length of leads:		REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:				
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown		
Lead condition:	_	4-Yellow	8-Red			
Lug type:		Connections As Re	eceived:			
Lug Condition:	-		Terminal	Lugs		
Lug size:						
Lug Attachment:	_					

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type:	Cast Aluminum		Rotor
Rotor Condition:	Ok	Num rotor bars: Num broken bars:	
Rotor Test Results			
Visual: Pass	Grow	ler: Pass	Single phase: Pass
Stator type:	Factory	If other, stator ty	pe:
Stator condition:	Ok	If other, stator conditi	on:
Failure location:	In slot	If other, stator failu	ıre:
Stator Image:		Failure Ima	ge:

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding col	or:	Like new	Winding	g image	Winding Therma	I Protection:	Yes
Winding conditio	n:	Solid	Ĩ	PERX 0452 0457 0457 0468 0670 0510			
Winding Thern Protection D		_					
Winding Thern Protection OE		_	The loss				
Stator test resu	lts:	Salvageable					
Megs incoming:	Goo	d	Surge incoming:	Good	Hi-pot in	coming: G	ood
Winding Resistar	nce In	coming					
	Phase	es A to B	Phases B to C	Phase	es C to A	Resistive imb	alance
Incoming	11.0		11.2	11.0		2.1	
Leads/	/jumpe	ers: Ok		Lead ju	umper Image:		
If other, leads/	/jumpe	ers:					

rs:

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Shaft key way wallowed and impeller showed signs of wear as well as key way worn.

Cause of Failure

Comments

Motor and pump assembly didn't turn freely on initial check. After removing the pump from the motor, the motor turned freely, and was tested and ran with no defects. Recommend replacing worn seal assembly and impeller, and repairing wallowed shaft key way.

Note: Motor is U.L. Spec.

Service Tech name: **Terrence Holland**

Service Tech signature:

Jerna Arla

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301