

Job Information

Job #: 94586

Date: August 31, 2018

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: Flushing Meadows

Reason:

Contact:

Motor#:

PO#:

Application: —

Special notes:

Name Plate Information

Manufacturer: Gould's

Enclosure : Open Drop Proof (ODP)

Enclosure Type image

Serial#: M1688

Model#: WS2012D3

Service Factor:

Frame:

Horsepower/kW: 2

Rated RPM: 1725

Rated Amps: 16

Rated Voltage: 230

Phase: 1

Cycles: 60

Special design: No



Nameplate

DE

ODE

F1

F2

Top



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device present?: No Contaminant Image:



Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: NSK

Insulated: No Bearing DE Size: 6206

Bearings ODE: Worn Bearings ODE make: NSK

Bearing Type: Ball Bearing ODE Size: 6204

Bearings Retainer: No Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type: Oil

Thermal Protection device DE: —

Lubrication brand inbound: Unknown

Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: N/A

Grease Cond. DE: New

Grease Amt ODE: N/A

Grease Cond. ODE: New

Seals DE type: Isolators

Seals Image:



Seals DE size:

Seals DE (inbound) condition : Cracked

Seals Image 2:



Seals ODE type: Isolators

Seals ODE size:

Seals ODE (inbound) condition : Good

Shaft damage cause: None

Shaft Image:



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Not Available



Water jacket: N/A



Not Available



Fan: Ok



Not Available



Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount

Endbell type: Single piece

Missing parts?

- | | | |
|--------------------------------------|----------------------------------|--|
| <input type="checkbox"/> J-Box cover | <input type="checkbox"/> O-rings | <input type="checkbox"/> J-Box |
| <input type="checkbox"/> HH cover | <input type="checkbox"/> Glands | <input checked="" type="checkbox"/> None |

Endbell Image:



Other missing parts

Mechanical Inspection (Continued)

Air Gap Measurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0	ODE @ 0	—
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads: —

Terminal Markings:

Length of leads: 6"

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:

Size of leads:

- | | | |
|----------|---------------------|----------------------|
| 1-Blue | 5-Black | P1-No color assigned |
| 2-White | 6-No color assigned | P2-Brown |
| 3-Orange | 7-No color assigned | |
| 4-Yellow | 8-Red | |

Lead condition: Good

Connections As Received:

Lug type:

Lug Condition: —

Terminal



Lugs



Lug size:

Lug Attachment: —

AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor

Rotor Condition: Ok

Num rotor bars:	47
Num broken bars:	0



Rotor Test Results

Visual: Pass

Growler: Pass

Single phase: Pass

Stator type: Factory

If other, stator type:

Stator condition: Ok

If other, stator condition:

Failure location: Other

If other, stator failure:

Stator Image:



Failure Image:



AC Electrical Inspection (Continued)

Winding color: Like new

Winding image

Winding Thermal Protection: Yes

Winding condition : Solid



Winding Thermal Protection DE: —

Winding Thermal Protection ODE: —

Stator test results: Salvageable

Megs incoming: Good

Surge incoming: Good

Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers: Ok

Lead jumper Image. :

If other, leads/jumpers:



Conclusion

Component Failure

Lower seal

Cause of Failure

Lower housing seal surface cracked

Comments

Found lower seal assembly face cracked. This allowed water to contaminate the oil in the housing. The stator windings checked good as well as the capacitors which checked at 40.5 u.f. on both.

Service Tech name: Terrence Holland

Service Tech signature:

