

Job Information

Job #: 94649

Date: August 24, 2018

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: Welspun

Reason:

Contact:

Motor#:

PO#:


Application: —

Special notes:

Name Plate Information

Manufacturer:	Siemens	Enclosure :	Totally Enclosed Fan Cooled
Serial#:	N8 204834	Model#:	1LAO 163-4YA91- Z
Service Factor:		Frame:	160M
Horsepower/kW:	11	Rated RPM:	1775
Rated Amps:	18	Rated Voltage:	460
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image



Nameplate



DE

ODE

F1

F2

Top



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Water

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device present?: No Contaminant Image:



Type of grounding device:

Shaft runout(TIR-Inbound): .001

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6209 C3

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6209 C3

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image




Bearing Make Image



Bearing Retainer Image



Thermal Protection



Not Available

Mechanical Inspection (Continued)

Lubrication Type: Grease

Thermal Protection device DE: —

Lubrication brand inbound: Unknown

Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: 1/2

Grease Cond. DE: Watery

Grease Amt ODE: 1/2

Grease Cond. ODE: Watery

Seals DE type: Slinger

Seals Image:




Seals DE size:

Seals DE (inbound) condition :

Seals ODE type: Slinger

Seals Image 2:



Seals ODE size:

Seals ODE (inbound) condition :

Shaft damage cause: None

Shaft Image:



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: Ok



Not Available



Fan: Ok



Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount

Endbell type: Single piece

Missing parts?

- | | | |
|--------------------------------------|----------------------------------|--------------------------------|
| <input type="checkbox"/> J-Box cover | <input type="checkbox"/> O-rings | <input type="checkbox"/> J-Box |
| <input type="checkbox"/> HH cover | <input type="checkbox"/> Glands | <input type="checkbox"/> None |

Endbell Image:



Other missing parts

Fan cover

Mechanical Inspection (Continued)

Air Gap Measurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0	ODE @ 0	—
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads: 6

Terminal Markings:

Length of leads: 6"

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:

Size of leads:

- | | | |
|----------|---------------------|----------------------|
| 1-Blue | 5-Black | P1-No color assigned |
| 2-White | 6-No color assigned | P2-Brown |
| 3-Orange | 7-No color assigned | |
| 4-Yellow | 8-Red | |

Lead condition: Good

Connections As Received:

Lug type:

Lug Condition: —

Terminal



Lugs



Lug size:

Lug Attachment: —

AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor

Rotor Condition: Ok

Num rotor bars:	37
Num broken bars:	0



Rotor Test Results

Visual: Pass

Growler: Pass

Single phase: Pass

Stator type: Factory

If other, stator type:

Stator condition: Ok

If other, stator condition:

Failure location: Other

If other, stator failure:

Stator Image:



Failure Image:



AC Electrical Inspection (Continued)

Winding color: Still has color

Winding image


Winding Thermal Protection: No

Winding condition : Solid

Winding Thermal Protection DE: —

Winding Thermal Protection ODE: —

Stator test results: Salvageable



Megs incoming: Good

Surge incoming: Good

Hi-pot incoming: Good

Winding Resistance Incoming

	Phases A to B	Phases B to C	Phases C to A	Resistive imbalance
Incoming	0.772	0.772	0.772	0

Leads/jumpers: Ok

Lead jumper Image :



If other, leads/jumpers:

Conclusion

Component Failure

Bearings. Also found both end bell housing bearing fits oversized.

Cause of Failure

Excessive amount of moisture penetrated stator housing, causing grease contamination leading to bearing failure.

Comments

Motor checked out bad and showed grounded from initial test. After disassembly I found evidence of an excessive amount of moisture having been present resulting in large quantities of rust inside the stator. Will wash and bake stator and reassess stator winding integrity. UPDATE: Stator assembly checked good after wash and bake.

Service Tech name: Terrence Holland

Service Tech signature:

