

Job Information

94423 Job #: Date: June 29, 2018

Priority: Authorized OT: No Authorized by:

Customer Information

Name: Synovos Reason:

Contact: Motor#: PO#:

Application: Special notes:

Name Plate Information

Manufacturer: Baldor Enclosure: Totally Enclosed **Enclosure Type image** Fan Cooled

W1704124515 35R755S811G2 Serial#: Model#:

Service Factor: 1.00 Frame: 145TCZ

Horsepower/kW: 2 Rated RPM: 3450

Rated Amps: 5.4-5/2.5 Rated Voltage: 208-230/460

Phase: 3 Cycles: 60

Special design:

No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301

Not



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Type of grounding device:

Available

Shaft runout(TIR-Inbound): .003"

Bearings DE: Other Bearings DE make: Other

Insulated: No Bearing DE Size:

Bearings ODE: Other Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size:

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image Bearing Make Image Bearing Retainer Image Thermal Protection

Not Not Not Not Available Available Available

ax 901-873-5301



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A Seals Image:

Seals DE size:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: None Shaft Image:

Co

CENTRAL ARKANSAS

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Seals Image 2:





Mechanical Inspection (Continued)

Brg. Image:

Bushings/sleeves image:

Not Available

Not Available

Water jacket:

N/A

Fan: 0

Ok

Frame cond.:

Good

Not Available



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

O-rings

☐ J-Box

☐ HH cover

Glands

■ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings:

Length of leads: 7" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned
4-Yellow 8-Red

Connections As Received: 460 volt

Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: — Available





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor

Ok

Num broken bars:

Num rotor bars:

Not Available

Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:

Not Available

Not Available

Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE: Not Available Available

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 5.069 5.064 5.067 0.1

Leads/jumpers: Ok Lead jumper Image. :

Not Available



Conclusion

Component Failure

Cause of Failure

Comments

Motor runs good, shaft has .003" runout, replace seal

Service Tech name: Lynn McDonald

Service Tech signature:

Fax 901-873-5301

Lynn M. Doneld