

## **Job Information**

Job #: 94976 Date: December 19,

2018

Priority: — Authorized OT: No Authorized by:

**Customer Information** 

Name: WELSPUN Reason:

Contact: Motor#: PO#:

Application: – Special notes:

**Name Plate Information** 

Serial#:

Manufacturer: Siemens Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

E080215121777010 Model#: 1LA91334KA60

04

Service Factor: 1.15 Frame:

Horsepower/kW: 7.5 Rated RPM: 1760

Rated Amps: 12.8 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: 

Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: Other

Insulated: No Bearing DE Size: 6208ZZ

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6208ZZ

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Other Seals Image:

Seals DE size: 40 47 5

Seals ODE type: Slinger

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: None Shaft Image:

Not Available

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 fax 501-375-4254



Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket:

Ok

Fan:

Ok

Frame cond.:

Good

Not Available





Endbell Image:



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ HH cover

Glands

☐ J-Box

None



Other missing parts

Fan cover



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90** 

DE @ 180 **ODE @ 180** 

DE @ 270 **ODE @ 270** 

## **AC Electrical Inspection**

Good

Lead condition:

Lug size:

Fax 901-873-5301

Number of leads: 6 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads:

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads:

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange 4-Yellow 8-Red

Connections As Received: High voltage Lug type:

Lug Condition: Terminal Lugs

Not Available Lug Attachment:

Fax 501-375-4254



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:



### **Rotor Test Results**

Visual: Pass Growler: Pass Single phase: Pass


Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition: Spun liamination

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







# **AC Electrical Inspection (Continued)**

Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal \_\_\_\_ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Not Available

Megs incoming: Bad Surge incoming: Good Hi-pot incoming: Good

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 1.067 1.063 1.145 7.3

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6208

Shaft runout(TIR-Inbound): Bearing ODE Size: 6208

Retainer condition: -



Seals DE condition: Broken Brg. Seats DE: Good

Seals DE type: Other If DE undersized, amt.:

Seals DE size: 40 47 5 Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: Slinger

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

3.1501 Good

Endbell fits/damage: Bad Foot/Flange condition: Ok

Endbell DE size: 3.1508 Bad Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

bers Wiley



## Conclusion

**Component Failure** 

**Cause of Failure** 

#### **Comments**

De Bearing housing fit bad Rotor drug laiminations caused motor to go to ground

Service Tech name: Robert Wiley

Service Tech signature: