

Job Information

Job #: 96248 Date: November 21,

2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Pinecrest Divison Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Siemens Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: Model#: 1LA04454FC41A

Service Factor: Frame: 445T

Horsepower/kW: 150 Rated RPM: 1800

Rated Amps: 175 Rated Voltage: 460

Phase: Cycles:

No

Nameplate DE ODE F1 F2 Top



Special design:











Fax 901-873-5301

CENTRAL ARKANSAS



present?:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Grease

Shaft rotation: Bi-directional Contaminant(s) Amt: Full

Shaft grounding device No Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: Koyo

Insulated: No Bearing DE Size: NU318

Bearings ODE: Worn Bearings ODE make: Koyo

Bearing Type: Ball Bearing ODE Size: 6316ZZ

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Hard

Grease Amt ODE: Full Grease Cond. ODE: Hard

Seals DE type: Slinger Seals Image:

Seals DE size:

Not

Available

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type:

N/A

Seals Image 2:

Not Available

Seals ODE size:

Shaft damage cause: None Shaft Image:



Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket: N/A



Fan: Ok



Endbell Image:

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

Missing parts?

✓ J-Box cover

O-rings

J-Box

☐ HH cover

Glands

■ None



Other missing parts



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA

spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 3 Terminal Markings: Orange Brown Yellow

Length of leads: 18" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: - Available

Not





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 36

Num broken bars:

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:





Not



AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Not Available

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Available

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: NU 318

Shaft runout(TIR-Inbound): Bearing ODE Size: 6316

Retainer condition: -

Fax 901-873-5301



Seals DE condition: None Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: 3.5439

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: 3.1498

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 7.4806 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

6.6944 Bad



Conclusion

Component Failure

Cause of Failure

Comments

.Ode bearing housing fit bad.both ends had mixed grease.missing J Box .Also over Greased

Robert Willy

Service Tech name: Robert Wiley

Service Tech signature:

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300

Fax 901-873-5301