

Job Information

Job #:	96664				Date:	March 16, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	lame: 3M			Reason:	
Contact:		Motor#:		PO#:	
Application:	_	Special notes:			

Name Plate Information

Manufacturer:	P&H	Enclosure :	Totally Enclosed Non-Ventilated
Serial#:	119027-18-A-11	Model#:	HEW-505
Service Factor:	1.15	Frame:	505
Horsepower/kW:	60	Rated RPM:	875
Rated Amps:	162/81	Rated Voltage:	460
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image



Nameplate

DE

ODE

F1

F2





Тор









WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Water
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			1

Bearings DE:	Worn	Bearings DE make:	
Insulated:	No	Bearing DE Size:	6317
Bearings ODE:	Worn	Bearings ODE make:	SKF
Bearing Type:	Ball	Bearing ODE Size:	6317
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	Watery
Grease Amt ODE:	Full	Grease Cond. ODE:	Watery
Seals DE type:	N/A	Seals Image:	
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A	Seals Image 2:	
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: Ok



Fan: Ok



Endbell Image:

Frame cond.: Good



Motor Mount Position:

Missing parts?

J-Box cover

HH cover

Horizontal/Foot mount

O-rings

Glands

J-Box

None

Endbell type:

Single piece

Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Pier	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	9	Terminal Markings:	1-9	
Length of leads:	16"	REF: NEMA Stds Markings Identifi	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	-	4-Yellow	8-Red	
Lug type:		Connections As Red	ceived: High voltage	9
Lug Condition:	_	1	Ferminal	Lugs
Lug size:				
Lug Attachment:	_			

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type:	Cast Aluminum	,		Rotor
Rotor Condition:	Ok	Num rotor bars: um broken bars:		
Rotor Test Results	i			
Visual: Pass	Growler:	Pass	Single phase:	Pass
Stator type:	Factory	If other, stator ty	/pe:	
Stator condition:	Ok	If other, stator conditi	ion:	
Failure location:	In slot	If other, stator fail	ıre:	
Stator Image:		Failure Ima	.ge:	

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	g image Wir	nding Thermal Protec	tion: No		
Winding condition :	Solid						
Winding Thermal Protection DE:							
Winding Thermal Protection ODE:							
Stator test results:	Rewind						
Megs incoming:	Bad	Surge incoming:	Good	Hi-pot incoming:	Bad		
Winding Resistance	Incoming						
Ph	ases A to B	Phases B to C	Phases C	to A Resisti	ve imbalance		
Incoming 0	.00	0.00	0.00	0.00			
Leads/jur	npers: Ok		Lead jun	nper Image. :			
If other, leads/jumpers:							
Mechanical In	spection						
Inspect bolt holes and fasteners. Validate correct fasteners.							

Shaft Condition:GoodBearings Retainer:YesType of grounding device:Bearing DE Size:6317Shaft runout(TIR-Inbound):Bearing ODE Size:6317

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	3.3468
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	3.3472
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Bad	Foot/Flange condition:	Ok
Endbell DE size:	7.0884 bad	Foot flatness:	Pass
Endbell DE insulated?:	No		stomer or EASA spec(<10%
Endbell ODE size:	7.0873 good	variation)?	
Endbell ODE insulated?:	No		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

Rewind stator and rotor .DE bearing Housing Fit BAD

Service Tech name:

Robert Wiley

Service Tech signature:

set Willer

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301