

Job Information

Job #: 97005 Date: June 26, 2020

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Saint jeans Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Serial#:

Manufacturer: Rotor Enclosure: Totally Enclosed Enclosure Type image

Model#:

Fan Cooled

Service Factor: Frame: 200LD

Horsepower/kW: 30kw Rated RPM: 2960

Rated Amps: 60/34.6 Rated Voltage: 400/690

Phase: 3 Cycles: 50

Special design: No

Nameplate DE ODE F1 F2 Top







Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Good Bearings DE make: FAG

Insulated: No Bearing DE Size:

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6312 2Z

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: 0 Grease Cond. ODE: Other

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals ODE size:

Seals ODE type:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: None

Slinger

Shaft Image:



Fax 901-873-5301



Water jacket: N/A Fan: Ok Frame cond.: Good





Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts





Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

Length of leads: 6" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: Acceptable





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars: 0 Rotor



Rotor Test Results

Rotor Condition:

Visual: Single phase: **Pass** Growler: Pass **Pass**

Stator type: If other, stator type: Factory

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image:





AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size:

Shaft runout(TIR-Inbound): Bearing ODE Size:

Retainer condition: Good

Phone 901-873-5300

Fax 901-873-5301



Seals DE condition :	Other	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	Slinger		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:		Foot flatness:	Pass
Endbell DE insulated?:	_	Does Air Gap Meet Cu	ustomer or EASA spec(<10%
Endbell ODE size:		variation)?	

Endbell ODE insulated?:



Conclusion

Component Failu	ıre
-----------------	-----

Cause of Failure

Brake rectifier bad

Comments

Brake assembly check good. Motor coils check good. O.D.E. bearing worn and needs replacing.

Town Holland

Service Tech name: Terrence Holland

Service Tech signature: