

7030 Ryburn Dr. Millington, TN

Phone: (901) 873-5300

Fax: (901) 873-5301

www.gohispeed.com

April 1, 2022

Tim Busby Mark Busby Atlantic Dry Ice Brandon, MS

Tim/Mark,

The following is a summary of findings from the quarterly vibration survey on the Ammonia Compressors at the Brandon, MS plant. Please let us know if there are any questions or comments.

QualiTest® uses a four step rating system for defects.

<u>Class I:</u> Defect is present, but effect on reliability is not clear; no immediate action is required. Continue to normally monitor.

<u>Class II</u>: Defect (s) present that may cause problem in long term (2-6 months). Repair during normal maintenance scheduling. Continue to monitor.

<u>Class III</u>: Defect (s) present that may cause failure in short term (less than 2 months). This should be addressed as soon as practical, with a high maintenance priority. Increase monitoring frequency.

<u>Class IV</u>: Defect (s) present that makes continued reliability unpredictable, and possibility of secondary damage is high. Repairs should be made ASAP. An unscheduled shutdown should be considered for repairs

Hi-Speed Industrial Service tests and inspects industrial machinery and equipment and makes recommendations concerning maintenance and repairs based on its experience in the field of industrial repair and maintenance. The information contained herein is provided as an opinion only, not as a guaranty or warranty of the matters discussed herein.

C-1 Ammonia Compressor

Data indicates another increase in 1 and 2 x rpm vibrations in the motor. This indicates coupling and or alignment issues. It is highly recommended to inspect the couplings for wear and ensure alignment is within tolerances. Hi-Speed provides alignment services. We have many years in shaft alignment experience and would be glad to perform this work for you. Rated as a **CLASS II** defect.

C-2 Ammonia Compressor

Motor remains to have a 120 Hz (2 x line frequency) vibration which may indicate some slight electrical issues in the rotor and or stator. Motor may have soft foot and stator could be slightly distorted and could be causing air-gap variations between rotor and stator. Compressor data still shows some signs of internal wear of the compressor. We will continue to monitor this closely. Motor is rated as a **CLASS I** defect and compressor is rated as a **CLASS II** defect.

C-3 Ammonia Compressor

Vibration data showed no issues were present during this survey. No actions recommended at this time.

				ntic Dry Ice don MS Plant		
MEASUE	REMENT	POINT	C	OVERALI	L LEVEL	HFD / VHFD
			-			
C-1	-	- c-1	AMMONIA	COMPRESSOR		(24-Mar-22)
				OVERAI	LL LEVEI	L 1K-20KHz
	MOH			. 375	In/Sec	.453 G-s
	MOV			.242	In/Sec	.194 G-s
	MIH			.198	In/Sec	.937 G-s
	MIV			.290	In/Sec	.443 G-s
	MIA			.275	In/Sec	.326 G-s
	CIA			.146	In/Sec	.199 G-s
	CIH			.167	In/Sec	.236 G-s
	CIV			.131	In/Sec	.243 G-s
	COH			.058	In/Sec	.344 G-s
	cov			.160	In/Sec	.292 G-s
C-2	-	- c-2	AMMONIA	COMPRESSOR		(24-Mar-22)
				OVERAI	LL LEVEI	L 1K-20KHz
	MOH			.149	In/Sec	.917 G-s
	MOV			.160	In/Sec	.917 G-s .355 G-s
	MIH			.119	In/Sec	.998 G-s
	MIV			.107	In/Sec	.250 G-s
	MIA					.323 G-s
	CIA				In/Sec	284 G-s
	CIH			.127	In/Sec	
	CIV			. 579	In/Sec	.628 G-s
	СОН			.152	In/Sec	1.117 G-s
	cov			.131	In/Sec	.488 G-s
C-3	-	- c-3	AMMONIA	COMPRESSOR		(24-Mar-22)
				OVERAI	LL LEVEI	L 1K-20KHz
	MOH			.053	In/Sec	.712 G-s
	MOV			.070	in/sec	.104 G-S
	MIH			.063	In/Sec	.528 G-s
	MIV			.080	In/Sec	.244 G-s
	MIA				In/Sec	
	CIA			.106	In/Sec	.169 G-s
	CIH				In/Sec	.350 G-s
	CIV			.089	In/Sec	.207 G-s
	COH			.059	In/Sec	.441 G-s
	cov			104	In/Sec	.367 G-s

Clarification Of Vibration Units: Acc --> G-s RMS Vel --> In/Sec PK

As always, it has been a pleasure to serve Atlantic Dry Ice. If there are any comments or questions, do not hesitate to contact us.

Sincerely,

Kevin W. Maxuell

ISO Certified Vibration Analyst, Category III



QualiTest Diagnostics Cell: 901-486-4565 Email: kwilliam@gohispeed.com