



8/11/2021 7:42:39 AM



8/11/2021 7:42:48 AM



Measurements

Sp1	145.3 °F
Sp2	151.5 °F
Sp3	141.8 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicates a high resistance connection on the load side and line side of phase B. The data also shows that the load side of the fuse is overheating. Replace the fuse and clean the fuse holder with sandpaper. Check the wire for damage. Replace if necessary, and repair as necessary tighten to proper torque.