

Job Information

Job #: 139038 Date: February 6, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: United Solutions Reason: Motor inspection

Contact: Debra Bolton Motor#: PO#:

Application: Direct Drive Special notes:

Name Plate Information

Manufacturer: US Enclosure : Open Drop Proof Enclosure Type image

(ODP)

Serial#: 97485-GY Model#: 4090D452200

Service Factor: Frame: 409ATZ

Horsepower/kW: 200 Rated RPM: 1750/1900

Volts 500 Volts 300

Amps 325 Amps 4.235

Nameplate DE ODE F1 F2 Top

Fields



Armature











Thermal Protection

Thermal Overloads



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Dirt

> Shaft rotation: **CCW** Contaminant(s) Amt: Other

Shaft Condition: Contaminant Image: Good

Shaft grounding device

No present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearing Type Image



Bearing Make Image



Lubrication Type: Grease

Lubrication brand inbound: Mobile Polyrex EM

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: 0

Grease Amt ODE: 0 Bearing Retainer Image



Thermal Protection device DE:

Thermal Protection device ODE:

Grease Cond. DE:

Grease Cond. ODE:

Other

Other

N/A


WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)



Size 18703

Shunt Len. 3 inches

Insulated No

TermType

Brg Image



Shaft Image



Brushing/sleeves



End bell



Water jacket: N/A



Fan: Ok



Frame cond.:





Motor Mount Position: Horizontal/Foot mount

Foot/Flange condition: Ok Foot flatness: Pass



Mechanical Inspection (Continued)

Missing parts?		
☐ J-Box cover ☐ O-rings ☐	J-Box HH cover	☐ Glands ☐ None
Other missing parts		
Air Gap Meaurements (N/A on Single Piece Endbell)		Does Air Gap Meet Customer or EASA spec(<10% variation)?
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	
Electrical Inspection		
Move armature imbalance to Assemble	Commutator:	Salvageable
Winding Inspection		
Meg Test IP to Flds: Good	Polarity Check IP to	Flds: —
Meg Series to Shunt: Bad		



DC Electrical Inspection

Brushes: Normal wear

Brush Image:

Brush holders:

Salvageable

8

8

Insulators:

Salvageable

Qty.

1000

Lead support stud:

Salvageable

Qty.

Qty.

Alternate brush image:

N. W. A.

Rocker ring:

Salvageable

Qty.

Commutator Type:

Tig welded

Commutator images

Commutator Hardness:

Good

Commutator Condition:

Salvageable

Commutator Film:

Ok



Armature images

Armature type:

Factory

If other

If other

Failure location:

Failure mode:

Other

Ok

If other

Armature condition:

Brittle

If other

Insulation

Winding color:

Still has color



DC Electrical Inspection (Continued)

Armature image

Armature Test Results

Megs: Good Hi-pot: Good Core loss: Good



Fields condition

Series/Stab condition: Shorted turn-turn Fields condition image:

Shunts condition: Shorted turn-turn

InterCoils condition: Replace



Fields test results

Series/Stab Meg: Bad Hi Pot: Ok Resistance: Ok

Shunts Meg: Bad Hi Pot: Ok Resistance: Ok

InterCoils Meg: Ok Hi Pot: Bad Resistance: Bad

Thermistors: In use Field Test image

RTD: None At

Thermostat: Open





Leads/jumpers: Ok

Lead jumper Image:



Conclusion

Component Failure

Fields interpoles and armature

Cause of Failure

Shorted stab shunt fields and INTERPOL's

Comments

Rewind everything. Fields Interpoles and armature

Service Tech name: Dan Mahan

Service Tech signature:

D_ M.