

### **Job Information**

Job #: 140708 Date: September 25,

2019

Priority: — Authorized OT: No Authorized by:

#### **Customer Information**

Name: INSTIUFORM Reason:

Contact: Motor#: 140708 PO#:

Application: – Special notes:

#### **Name Plate Information**

Manufacturer: LEROY SOMER Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: 664785/01-07795 Model#:

Service Factor: Frame:

Horsepower/kW: 52kw Rated RPM: 3100

Volts 440 Volts 360

Amps 132 Amps 2.2

Nameplate DE ODE F1 F2 Top

**Fields** 



Armature











Fax 901-873-5301



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Carbon

Shaft rotation: — Contaminant(s) Amt: Other

Shaft Condition: Good Contaminant Image:

Shaft grounding device

present?:

Type of grounding device:

Shaft runout(TIR-Inbound): .001



Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type:

Grease

Thermal Protection device DE:

N/A

Lubrication brand inbound:

Mobile Polyrex EM

Thermal Protection device ODE:

N/A

Lubrication brand outbound:

Mobile Polyrex EM

Grease Cond. DE:

Other

Grease Amt DE:

0

Grease Cond. ODE:


Other


Grease Amt ODE: Full

ax 901-873-5301



# **Mechanical Inspection (Continued)**





Brg Image



Shaft Image



Brushing/sleeves



End bell



Water jacket: Ok



Fan: Ok



Frame cond .:



Good

Motor Mount Position:

Horizontal/Foot mount

Foot/Flange condition:

Ok

Foot flatness:

Pass



# **Mechanical Inspection (Continued)**

	-	•		•					
Missin	g parts?								
<b>☑</b> J-Bo	ox cover	O-rings		J-Box	HH cover		Glands		None
Other m	issing parts								
Air Gap Meaurements (N/A on Single Piece Endbell)						Does Air Gap Meet Customer or EASA spec(<10% variation)?			
	DE @ 0			ODE @ 0		_			
	DE @ 90			ODE @ 90					
	DE @ 180			ODE @ 18	0				
	DE @ 270			ODE @ 27	0				

# **Electrical Inspection**

✓ Move armature imbalance to Assemble Commutator: Salvageable

# **Winding Inspection**

Meg Test IP to Flds: Good Polarity Check IP to Flds: Yes

Meg Series to Shunt: Good

Brush Image:



# **DC Electrical Inspection**

Brush holders:

Brushes: Normal wear

Salvageable Qty. 4

Insulators: Salvageable Qty.

Lead support stud: Salvageable Qty. Alternate brush image:

Rocker ring: Salvageable Qty. 1





Commutator Type: Tig welded

Commutator Hardness: Good

Commutator Condition: Salvageable

Commutator Film: Ok

Commutator images





Armature type: Factory

If other

Armature images

Failure mode:

Ok

If other

Failure location:

Front V ring

If other

Armature condition:

Solid

If other

Winding color:

Still has color

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd.

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



## **DC Electrical Inspection (Continued)**

#### Armature image

Armature Test Results

Megs: Good Hi-pot: Good Core loss: Good



Fields condition

Series/Stab condition: Ok Fields condition image:

Shunts condition: Ok

InterCoils condition: Ok



Fields test results

Series/Stab Meg: Ok Hi Pot: Ok Resistance: Ok

Shunts Meg: Ok Hi Pot: Ok Resistance: Ok

......

InterCoils Meg: Ok Hi Pot: Ok Resistance: Ok

Thermistors: None Field Test image

RTD: None At

Thermostat: None





Leads/jumpers: Replace

Lead jumper Image:



### Conclusion

#### **Component Failure**

Leads are bad

#### **Cause of Failure**

Field leads are blown into

#### Comments

Order two new 6310zz Clclean parts Turn undercut comm Balance arm Replace field leads

Service Tech name: Michael

Service Tech signature: