

Job Information

Job #: 95210

Date:

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: Cameron

Reason:

Contact:

Motor#:

PO#:

Application: —

Special notes:

Name Plate Information

Manufacturer: Westinghouse

Enclosure : Open Drop Proof (ODP)

Enclosure Type image

Serial#: 2002290

Model#: 5b284a18

Service Factor:

Frame:

Horsepower/kW:

Rated RPM:



Armature

Volts 230

Amps 9.3

Fields

Volts 230

Amps 1.6

Nameplate

DE

ODE

F1

F2

Top



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes

Contaminant(s): Oil

Shaft rotation: Bi-directional

Contaminant(s) Amt: Other

Shaft Condition: Good

Contaminant Image:

Shaft grounding device present?: No



Type of grounding device:

Shaft runout(TIR-Inbound): 0.001


Bearing Type Image




Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Oil

Thermal Protection device DE: —

Lubrication brand inbound: Unknown

Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full

Grease Cond. DE: Other

Grease Amt ODE: Full

Grease Cond. ODE: Other

Mechanical Inspection (Continued)

Brushholders

Number	4
Condition	Good
Size	
Spring type	Spring

Brushes

Number	4
Size	
Shunt Len.	2 inches
Insulated	No
TermType	


Brg Image



Shaft Image




Brushing/sleeves




End bell



Water jacket: N/A



Fan: N/A



Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount

Foot/Flange condition: Ok

Foot flatness: Pass



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

Missing parts?

☐ J-Box cover

☐ O-rings

☐ J-Box

☐ HH cover

☐ Glands

☒ None

Other missing parts

Air Gap Measurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0

ODE @ 0

—

DE @ 90

ODE @ 90

DE @ 180

ODE @ 180

DE @ 270

ODE @ 270

Electrical Inspection

☐ Move armature imbalance to Assemble

Commutator: Salvageable

Winding Inspection

Meg Test IP to Flds: Good

Polarity Check IP to Flds: Yes

Meg Series to Shunt: Good

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254

DC Electrical Inspection

Brushes: Normal wear

Brush Image:




Brush holders: Salvageable Qty. 4

Insulators: Salvageable Qty. 4

Lead support stud: Salvageable Qty. 4

Alternate brush image:



Rocker ring: Salvageable Qty. 1

Commutator Type: Soldered

Commutator images

Commutator Hardness: Good

Commutator Condition : Salvageable

Commutator Film: Ok



Armature type: Factory If other


Failure mode: Ok If other

Failure location: Other If other

Armature condition: Solid If other

Winding color: Painted

Armature images




DC Electrical Inspection (Continued)

Armature Test Results

Megs: Good Hi-pot: Good Core loss: Good

Armature image



Fields condition

Series/Stab condition: Ok

Fields condition image:

Shunts condition: Ok

InterCoils condition: Ok



Fields test results

Series/Stab Meg: Ok

Hi Pot: Ok

Resistance: Ok

Shunts Meg: Ok

Hi Pot: Ok

Resistance: Ok

InterCoils Meg: Ok

Hi Pot: Ok

Resistance: Ok

Thermistors: None

Field Test image

RTD: None

At



Thermostat: None

Leads/jumpers: Ok

Lead jumper Image:



Conclusion

Component Failure

Brushes weren't making contact with commutator.


Cause of Failure

Brushes were stuck in the brush rack.

Comments

Service Tech name: Trevor Hall

Service Tech
signature:

A handwritten signature in black ink, appearing to read 'Trevor Hall', written over a white background.