



Fiberglass
2ND Pass Paint Heater Panel
Panel # VFDIIXX
Fuse with X marked on it

8/11/2021 7:42:39 AM



8/11/2021 7:42:48 AM



Measurements

Sp1	143.2 °F
Sp2	139.5 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicates a high resistance connection on the load side and line side of phase A. The data also shows that the load side of the fuse is overheating. Replace the fuse and clean the fuse holder with sandpaper. Check the wire for damage. Replace if necessary, and repair as necessary. Tighten to proper torque.

It's the fuse right of CR1500 with X marked on it.