





Client	Penn A Kem	Survey Date	4-22-2020
Location	Memphis, TN	Report Date	4-23-2020
Machine	C56-51 Twin Screw Compressor	QMS No.	142350
Component	Lobe Pass	Analyst	DWS

Defect Rating for this machine	Class II
Defect Rating System	
Class I: Defect is present, but effect on reliability is not clear; no immediate action is required. Continue normal monitoring.	Class III: Defect (s) present that may cause failure in short term (less than 2 mos.). Should be addressed as soon as practical, with a high maintenance priority. Increase monitoring frequency.
Class II: Defect (s) present that may cause problem in long term (2-6 mos.). Repair during normal maintenance scheduling. Continue to monitor.	Class IV: Defect (s) present that makes continued reliability unpredictable, and possibility of secondary damage is high. Repairs should be made ASAP. An unscheduled shutdown should be considered for repairs.

Vibration Data	Analysis
<p>NEW - AXIAL TWIN SCREW COMPRESSOR C57-51 - 52 MALE-OPP END VERT</p>  <p>Route Spectrum 22-Apr-20 10:12:58</p> <p>OVERALL= .3439 V-DG PK = .3427 LOAD = 100.0 RPM = 1430. (23.84 Hz)</p> <p>Freq: 11.93 Ordr: .500 Spec: .00073</p>	<p>Dominant lobe pass vibrations peak in the spectrum of the male blower shaft.</p>

Discussion / Repair recommendations	Trend Data
<p>Low level harmonics, or possibly sidebands of female shaft speed and 2x/4x vibrations of Male shaft speed are evident in the gear end of the Male shaft. No significant bearing defect frequency vibration peaks have suggested distress in the bearings yet. Lobe pass vibrations dominate the data up to our current F-max. We believe the unit is under high load and or the lobe clearances are reduced and allowing possible contact between the rotors. We need to confirm the gear mesh frequency. Please provide tooth count.</p> <p>Rated a Class II Defect.</p>	 <p>Max Amp 28 Plot Scale 0.30</p> <p>PK Velocity in in/sec</p> <p>Frequency in Hz</p> <p>22-Apr-20 10:12:58 RPM= 7156</p> <p>Freq: 95.63 Ordr: 8.018 Sp 6: .284 Clng: .00000</p>



Client	Penn A Kem	Survey Date	4-22-2020
Location	Memphis, TN	Report Date	4-23-2020
Machine	P4C-102A Boiler Feed Water Pump	QMS No.	142350
Component	Bearings	Analyst	DWS

Defect Rating for this machine	Class II
Defect Rating System	
Class I: Defect is present, but effect on reliability is not clear; no immediate action is required. Continue normal monitoring.	Class III: Defect (s) present that may cause failure in short term (less than 2 mos.). Should be addressed as soon as practical, with a high maintenance priority. Increase monitoring frequency.
Class II: Defect (s) present that may cause problem in long term (2-6 mos.). Repair during normal maintenance scheduling. Continue to monitor.	Class IV: Defect (s) present that makes continued reliability unpredictable, and possibility of secondary damage is high. Repairs should be made ASAP. An unscheduled shutdown should be considered for repairs.

