

December 3, 2020

Most

Subject: December Dust Collector vibration service

Both units need attention, but at different ratings. Supporting data follows.

QualiTest® uses a four step rating system for defects.

<u>Class I:</u> Defect is present, but effect on reliability is not clear; no immediate action is required. Continue to normally monitor.

<u>Class II</u>: Defect (s) present that may cause problem in long term (2-6 months.). Repair during normal maintenance scheduling. Continue to monitor.

<u>Class III</u>: Defect (s) present that may cause failure in short term (less than 2 months.). This should be addressed as soon as practical, with a high maintenance priority. Increase monitoring frequency.

<u>Class IV;</u> Defect (s) present that makes continued reliability unpredictable, and possibility of secondary damage is high. Repairs should be made ASAP. An unscheduled shutdown should be considered for repairs

Hi-Speed Industrial Service tests and inspects industrial machinery and equipment and makes recommendations concerning maintenance and repairs based on its experience in the field of industrial repair and maintenance. The information contained herein is provided as an opinion only, not as a guaranty or warranty of the matters discussed herein.

This completes our assessment of your equipment for this survey. Thank you for your business and don't hesitate to call if you have any comments or questions.

Sincerely,

David W. Shook Senior Reliability Specialists *Hi-Speed* Industrial Service dshook@gohispeed.com

> 7030 Ryburn Drive Millington, TN 38053 P. 901-873-5300 F. 901-873-5301

South Dust Collector Fan



The south fan bearings seem to be in distress. Multiple 1/3 order harmonics vibrations plus random impacting and a 1x RPM vibration over 0.3"/second in the horizontals. Fractional harmonics are not good. We believe high vibrations over time have degraded them. Bearing replacement would be prudent due to the duty cycle of these units. **Rated a Class II Defect.**

North Dust Collector Fan



The North fan looks to have some bearing wear and a few normal shaft speed harmonics. Inspect the bearings, purge the grease and re-lubricate s specified by manufacturer. Inspect the coupling, re-lube and have the alignment checked. Rated a Class I Defect

Abbreviated Last Measurement Summary Database: Analysis.rbm Area: ANALYSIS 2 Report Date: 03-Dec-20 13:23 OVERALL LEVEL MEASUREMENT POINT HFD / VHFD -----_____ _____ S BAGHOUSE - MOST SOUTH BAGHOUSE FAN (03-Dec-20) OVERALL LEVEL
 OVERALL LEVEL
 1K-20KHz

 .130 In/Sec
 1.103 G-s

 .069 In/Sec
 .203 G-s

 .117 In/Sec
 .625 G-s

 .081 In/Sec
 .647 G-s

 .086 In/Sec
 .620 G-s

 .321 In/Sec
 .808 G-s

 .366 In/Sec
 .808 G-s

 .346 In/Sec
 .138 G-s

 .384 In/Sec
 .266 G-s
 1K - 20KHzMOH - MOTOR OUTBOARD HORIZONTAL MOV - MOTOR OUTBOARD VERTICAL MIH - MOTOR INBOARD HORIZONTAL MIV - MOTOR INBOARD VERTICAL MIA - MOTOR INBOARD AXIAL EIA - EQUIPMENT INBOARD AXIAL EIH - EQUIPMENT INBOARD HORIZONTAL EIV - EQUIPMENT INBOARD VERTICAL EOH - EQUIPMENT OUTBOARD HORIZONTAL .384 In/Sec .266 G-s EOV - EQUIPMENT OUTBOARD VERTICAL .340 In/Sec .240 G-s _____ Clarification Of Vibration Units: Acc --> G-s RMS Vel --> In/Sec PK Abbreviated Last Measurement Summary ********************************* Database: Analysis.rbm Area: ANALYSIS 2 Report Date: 03-Dec-20 13:25 MEASUREMENT POINT OVERALL LEVEL HFD / VHFD _____ _____ -----N BAGHOUSE - MOST NORTH BAGHOUSE FAN (03-Dec-20)

 (03-Dec-20)

 OVERALL LEVEL
 1K-20KHz

 .059 In/Sec
 .394 G-s

 .039 In/Sec
 .446 G-s

 .051 In/Sec
 .110 G-s

 .057 In/Sec
 .391 G-s

 .046 In/Sec
 .515 G-s

 .291 In/Sec
 .435 G-s

 .125 In/Sec
 .631 G-s

 .088 In/Sec
 .444 G-s

MOH - MOTOR OUTBOARD HORIZONTAL MOV - MOTOR OUTBOARD VERTICAL MIH - MOTOR INBOARD HORIZONTAL MIV - MOTOR INBOARD VERTICAL MIA - MOTOR INBOARD AXIAL EIA - EQUIPMENT INBOARD AXIAL EIH - EQUIPMENT INBOARD HORIZONTAL EIV - EQUIPMENT INBOARD VERTICAL .444 G-s EOH - EQUIPMENT OUTBOARD HORIZONTAL .088 In/Sec .112 In/Sec .484 G-s EOV - EQUIPMENT OUTBOARD VERTICAL Clarification Of Vibration Units: Acc --> G-s RMS

Vel	> In/Se	C PK			Abbreviated	Last	Measurement
Summary ************************************							
	Database: Area: Report Dat	Analysis.rb ANALYSIS 2 a: 03-Dec-20	n D 13:26				
MEASU	JREMENT POIN	r -	0	VERAL	L LEVEL	HFD	/ VHFD
S BAGHOUSE	- MOST SOUT	H BAGHOUSE F	AN (03-Dec OVERAI	2-20) LL LEVEL	1K-20)KHz
MOH – MOTOF MOV – MOTOF	R OUTBOARD H	ORIZONTAL ERTICAL		.130	In/Sec In/Sec	1.103) G-s } G-s
MIH - MOTOR	R INBOARD HO	RIZONTAL		.117	In/Sec	. 625	j G-s / G-s
MIA - MOTOR	R INBOARD AX			.086	In/Sec	. 620) G-s
EIH - EQUIE	PMENT INBOAR	D HORIZONTAL		.366	In/Sec	. 808	G-S G-S
EIV - EQUIE EOH - EQUIE	PMENT INBOAR PMENT OUTBOA	D VERTICAL RD HORIZONTAL	L	.346	In/Sec In/Sec	.138	G-s G-s
FOA - FÖDIF	PMENT OUTBOA	KD VERTICAL		.340	IN/Sec	.240	/ G-S
Clarificati	ion Of Vibra	tion Units:					

Tartroad	.011 01	* TOTACT	JII 011110
Acc	>	G-s	RMS
Vel	>	In/Sec	PK