





Client	Almatis	Survey Date	8/31/20
Location	Benton	Report Date	9/1/20
Machine	Calcine Lift Blower #2	QMS No.	97224
Component	Motor	Analyst	WR



Defect Rating for this machine	<b>CLASS II</b>
Defect Rating System	
<b>Class I:</b> Defect is present, but effect on reliability is not clear; no immediate action is required. Continue normal monitoring.	<b>Class III:</b> Defect (s) present that may cause failure in short term (less than 2 mos.). Should be addressed as soon as practical, with a high maintenance priority. Increase monitoring frequency.
<b>Class II:</b> Defect (s) present that may cause problem in long term (2-6 mos.). Repair during normal maintenance scheduling. Continue to monitor.	<b>Class IV:</b> Defect (s) present that makes continued reliability unpredictable, and possibility of secondary damage is high. <b>Repairs should be made ASAP. An unscheduled shutdown should be considered for repairs.</b>

Vibration Data	Analysis
<p>Almatis-Calcine rbm / CLCN / #2 LIFT BLOWER MIV - MOTOR INBOARD VERTICAL</p>  <p>8/31/2020 10:01:01 AM Route 0.557 V-DG Pk = 0.558 LOAD = 100.00 RPM = 450.00 (7.500 Hz)</p> <p>Freq: 7.500 Ord: 1.000 Amp: 0.0279</p>	<p>1x peak with harmonics and a raised noise floor.</p> <p>Raised noise floor and harmonics could be an indication of a looseness issue.</p>
Discussion / Repair recommendations	Time Waveform
<p>We suggest an inspection of the motor, including a lift check, and run out check on the shaft to see if the looseness can be found. We also recommend a torque inspection of all fasteners for proper torque.</p> <p><b>CLASS II</b></p>	 <p>Almatis-Calcine rbm / CLCN / #2 LIFT BLOWER MIV - MOTOR INBOARD VERTICAL</p> <p>8/31/2020 10:01:01 AM Route RPM = 450.00 (7.500 Hz) LOAD = 100.00 RMS = 1.183 PK = 0.558 PK-C = 0.492 OPK = 0.242</p>



Client	Almatis	Survey Date	8/31/20
Location	Benton	Report Date	9/1/20
Machine	Calcine #1 Primary Fan	QMS No.	97244
Component	Motor	Analyst	WR



Defect Rating for this machine	<b>CLASS II</b>
Defect Rating System	
<b>Class I:</b> Defect is present, but effect on reliability is not clear; no immediate action is required. Continue normal monitoring.	<b>Class III:</b> Defect (s) present that may cause failure in short term (less than 2 mos.). Should be addressed as soon as practical, with a high maintenance priority. Increase monitoring frequency.
<b>Class II:</b> Defect (s) present that may cause problem in long term (2-6 mos.). Repair during normal maintenance scheduling. Continue to monitor.	<b>Class IV:</b> Defect (s) present that makes continued reliability unpredictable, and possibility of secondary damage is high. <b>Repairs should be made ASAP. An unscheduled shutdown should be considered for repairs.</b>





Client	Almatis	Survey Date	8/31/20
Location	Benton	Report Date	9/1/20
Machine	Calcine #3 Cooling Water Pump	QMS No.	97244
Component	Pump	Analyst	WR

Defect Rating for this machine	<b>CLASS IV</b>
Defect Rating System	
<b>Class I:</b> Defect is present, but effect on reliability is not clear; no immediate action is required. Continue normal monitoring.	<b>Class III:</b> Defect (s) present that may cause failure in short term (less than 2 mos.). Should be addressed as soon as practical, with a high maintenance priority. Increase monitoring frequency.
<b>Class II:</b> Defect (s) present that may cause problem in long term (2-6 mos.). Repair during normal maintenance scheduling. Continue to monitor.	<b>Class IV:</b> Defect (s) present that makes continued reliability unpredictable, and possibility of secondary damage is high. <b>Repairs should be made ASAP. An unscheduled shutdown should be considered for repairs.</b>

Vibration Data	Analysis
<p>Almatis-Calcine rbm / CLCN / #3-COOLING WATER PUMP PIV - PUMP INBOARD VERTICAL</p>  <p>8/31/2020 10:16:34 AM Route: 0.270 V-DO Pk = 0.270 LOAD = 100.00 RPM = 1785.0 (29.75 Hz) Freq: 29.75 Crs: 1.000 Amp: 0.00579</p>	<p>Non-synchronous peaks throughout the spectrum with a raised noise floor throughout.</p> <p>Non-synchronous peaks and raised noise floor could indicate a bearing or gear mesh issue.</p>
Discussion / Repair recommendations	Time Waveform
<p>We suggest an inspection of the bearings of this pump to see where the degradation is. This asset is thought to be in extreme danger of failure.</p> <p><b>CLASS IV</b></p>	 <p>Almatis-Calcine rbm / CLCN / #3-COOLING WATER PUMP PIV - PUMP INBOARD VERTICAL</p> <p>8/31/2020 10:16:34 AM Route: RPM = 1785.0 Crs: 1.000 LOAD = 100.00 RMS = 2.010 PK = 10.47 PK-A = 0.00579</p>