



DC Repair Report

Arkansas Box

100 William J Clark Drive
Conway, AR 72032

FolderID: 102301
FormID: 18961406

DC Repair Report Rev. 2

Location: MOTOR SHOP LR
Job Number: 102301
Serial Number: 44596-AL
Status: In For Repair
Description: 30HP ELECTROSTAT DC 2500RPM 327AT

Hi-Speed Job Number: 102301
Manufacturer: Other
Product Number : 32700350013
Serial Number: 44596-AL
HP/KW: 30 (HP)
RPM: 2500
Frame: 327AT
Armature Voltage: 500 (Volts)
Armature Current: 49 (Amps)
Field Voltage: 300 (Volts)
Field Current : 1.68 (Amps)
J-Box Included: Yes
Bearing RTDS: No
Winding RTDS: No
Mounting Orientation : Horizontal

Priorities Found: ● 1 - High ● 7 - Good

Overall Condition



1. Describe the Overall Condition of the Equipment as Received
Serviceable
2. Nameplate Picture

P17











3. Distance From the End of the Shaft to the end of the Face of the Sheave/Coupling

Initial Mechanical/Electrical



4. Does the Shaft Turn Freely?

(Y) Yes

5.	Does Shaft Have Visible Damage?	(No) No	P22
			
6.	Assembled Shaft Runout	0.001 Inches	
7.	Assembled Shaft End Play	0 Inches	
8.	Air Gap Variation <10%		
9.	Lead Condition	(P) Pass	P55
			
10.	Lead Length	Inches	
11.	Frame Condition	(P) Pass	
12.	Fan Condition	(P) Pass	P81
	Front fan.		
<div>   </div>			

13. Brush Information

P87

Brush Number

Quantity

Condition

4

replace



14. Brush Holder Condition - Verify proper gap to Commutator

P92



Incoming Electrical Test



15. General Condition of the Armature/Commutator

worn un-evenly

P6



97.8 G ohms



17. Field Circuit Insulation Resistance to Ground

18. Interpole Circuit Insulation Resistance to Ground

19. Total Field Ohms

20. Field Ohms

Between F1/F2

Between F3/F4

127.5

127.5

F1&F4. F2&F3

21. MegOhms between Fields and Series

22. Series Drop Test 1&2

Series 1

Series 2

23. Series Drop Test 3&4

Series 3

Series 4

24. Field Drop Test Fields 1&2

Total AC Voltage

Field #1

Field #2

115

0.42

0.424

25. Field Drop Test Fields 3&4

Field #3

Field #4

26. Field Drop Test Fields 5&6

Field #5

Field #6

27. Field Drop Test Fields 7&8

Field #7

Field #8

28. Interpole Drop Test 1&2

Total AC Voltage

Interpole #1

Interpole #2





1.97

1.97

29. Interpole Drop Test 3&4

Interpole #3

Interpole #4

30.	Interpole Drop Test 5&6	
	Interpole #5	Interpole #6
31.	Interpole Drop Test 7&8	
	Interpole #7	Interpole #8
32.	Armature Number of Bars - Bar to Bar Test	
	Number of Bars	Bar to Bar Test
	120	pass?
	 Used growler to test bar to bar. Shorted several bars together, and armature pulled.	
Mechanical Inspection 		
33.	Shaft Runout Drive End	0.001 inches
34.	Shaft Runout Armature	
	Drive End Bearing Journal	Armature Core ODE Bearing Journal
35.	Drive End Bearing Number	NTN 63211 LB P28
	<div style="display: flex; justify-content: space-around;">   </div>	
36.	Drive End Bearing Quantity	1
37.	Drive End Bearing Type	(Ball) Ball Bearing
38.	Drive End Lubrication Type	(Grease) Grease Lubricated
39.	Drive End Bearing Insulation or Grounding Device?	(NA)
40.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	none
41.	Drive End Bearing Condition	replace



Caused by grease contamination.

- | | |
|--|----------------------------|
| 43. Opposite Drive End Bearing Quantity | 1 |
| 44. Opposite Drive End Bearing Type | (Ball) Ball Bearing |
| 45. Opposite Drive End Lubrication Type | (Grease) Grease Lubricated |
| 46. Opposite Drive End Bearing Insulation or Grounding Device? | |
| None | |
| 47. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device? | none |
| 48. Opposite Drive End Bearing Condition | replace |
| 49. Signature of Technician who Performed Teardown | Terrence Holland |

50. List Parts Needed Prior to Reassembly
Bearings, sleeve D.E housing fit.

Mechanical Fits - Armature



51. Coupling Fit Closest to Bearing Housing

0 Degrees	60 degrees	120 degrees
-----------	------------	-------------

52. Coupling Fit Closest to the End of the Shaft

0 Degrees	60 degrees	120 degrees
-----------	------------	-------------

53. Drive End Bearing Shaft Fit

0 Degrees	60 Degrees	120 Degrees
2.1656	2.1654	2.1655



55. Opposite Drive End Bearing Shaft Fit			
0 Degrees	60 Degrees	120 Degrees	
1.9686	1.9685	1.9687	



57. Shaft Air Seal Fits		
Drive End Air Seal	Opposite Drive End Air Seal	

58. Drive End - End Bell Bearing Fit

P9

0 Degrees

60 Degrees

120 Degrees

3.5445

3.5446

3.5446



59. Drive End - Endbell Bearing Fit Condition

(F) Fail

P18

Excessive pitting and wear.

60. Opposite Drive End - End Bell Bearing Fit

0 Degrees

60 Degrees

120 Degrees

3.5436

3.5434

3.5435

61. Opposite Drive End - Endbell Bearing Fit Condition

(NA) Not Applicable

62. Bearing Cap Condition

Drive End

Opposite Drive End

63. End Bell Air Seal Fits

Drive End Air Seal

Opposite Drive End Air Seal

64. List any Machine work Needed Below

D.E housing fit bad

65. Signature of Technician Performing Measurements

Terrence Holland



Root Cause of Failure

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

66.	Failure Locations <i>Both bearings worn from grease contamination. D.E housing fit pitted possibly from minute electrical discharge. Comm is unevenly worn and needs undercut and turned.</i>		
67.	Root Cause of Failure		
Commutator Data			
68.	Total Copper Segment Length		
69.	Number of Bars		
70.	Number of Wires Per Copper Bar and Size		
	Number of Wires per Bar	Wire Size	
71.	Equalizers per Copper Bar and Equalizer Wire Size		
	Equalizers per Bar	Wire Size	
72.	Document Commutator Diameter, Minimum and Max		
	Current Comm Diameter	Minimum Comm Diameter	Maximum Comm Diameter
73.	Commutator Shaft Diameter		
	Front Shaft Diameter	Back Shaft Diameter	
74.	Commutator Type		
75.	Commutator Bore		
76.	Signature of Technician Recording Data		
Dynamic Balance Report			
77.	Rotor Weight and Balance Grade		
	Rotor Weight	Balance Grade	
78.	Initial Balance Readings		
	Drive End Readings	Opposite Drive End Readings	
79.	Final Balance Readings		
	Drive End Readings	Opposite Drive End Readings	
80.	Signature of the Balance Technician		
Post Armature Rewind Testing			
81.	Post Rewind Armature Insulation Resistance to Ground		
82.	Post Rewind Field Circuit Measure the Insulation Resistance to Ground		
83.	Post Rewind Armature Number of Bars - Bar to Bar Test		
	Number of Bars	Bar to Bar Test	
84.	Post Rewind Field Circuit Insulation Resistance to Ground		
85.	Post Rewind Interpole Circuit Insulation Resistance to Ground		
86.	Post Rewind Field Drop Test Fields 1&2		
	Total AC Voltage	Field #1	Field #2
87.	Post Rewind Field Drop Test Fields 3&4		
	Field #3	Field #4	

88.	Post Rewind Field Drop Test Fields 5&6		
	Field #5	Field #6	
89.	Post Rewind Field Drop Test Fields 7&8		
	Field #7	Field #8	
90.	Post Rewind Interpole Drop Test 1&2		
	Total AC Voltage	Interpole #1	Interpole #2
91.	Post Rewind Interpole Drop Test 3&4		
	Interpole #3	Interpole #4	
92.	Post Rewind Interpole Drop Test 5&6		
	Interpole #5	Interpole #6	
93.	Post Rewind Interpole Drop Test 7&8		
	Interpole #7	Interpole #8	
Post Mechanical Repair			
94.	Post Repair Coupling Fit Closest to Bearing Housing		
	0 Degrees	60 degrees	120 degrees
95.	Post Repair Coupling Fit Closest to the End of the Shaft		
	0 Degrees	60 degrees	120 degrees
96.	Post Repair Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
97.	Post Repair Drive End Bearing Shaft Fit Condition		
98.	Post Repair Drive End Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
99.	Post Repair Drive End Opposite Drive End Bearing Shaft Fit Condition		
100.	Post Repair Drive End - End Bell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
101.	Post Repair Drive End - Endbell Bearing Fit Condition		
102.	Post Repair Opposite Drive End - End Bell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
103.	Post Repair Opposite Drive End - Endbell Bearing Fit Condition		
104.	Post Repair Bearing Cap Condition		
	Drive End	Opposite Drive End	
105.	Post Repair End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	

106.	Signature of Tech Performing Mechanical Repairs		
Assembly			
107.	Take Pictures of all Major Components Prior to Reassembly		
108.	Verify Brush Box Holders Have the Proper Clearance, and Brushes have been Seated Properly		
109.	Assembled Shaft End Play and Runout		
	Shaft Endplay	Shaft Runout	
110.	Perform No-Load Test Run, Record Armature Voltage and Current		
	Voltage	Current	
111.	Perform No-Load Test Run, Record Field Voltage and Current		
	Voltage	Current	
112.	Document Vibration Readings Drive End		
	Horizontal	Vertical	Axial
113.	Document Vibration Readings Opposite Drive End		
	Horizontal	Vertical	Axial
114.	Perform Full-Load Test Run, Record Armature Voltage and Current		
	Voltage	Current	
115.	Perform Full-Load Test Run, Record Field Voltage and Current		
	Voltage	Current	
116.	Document Vibration Readings Under Full Load Drive End		
	Horizontal	Vertical	Axial
117.	Document Vibration Readings Under Full Load Opposite Drive End		
	Horizontal	Vertical	Axial
118.	Ambient Temperature		
119.	Drive End Bearing Temps Under Full Load		
	5 Minutes	10 Minutes	15 Minutes
120.	Opposite Drive End Bearing Temps Under Full Load		
	5 Minutes	10 Minutes	15 Minutes
121.	Final Test Run Sign-Off		
122.	Document Final Condition With Pictures		
123.	Final QC Sign-Off		