

LR Motor Shop

Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 102593 FormID: 19644628

AC Inspection as Found Novus Arkansas, LLC (11612)

7920 Sloan Drive Little Rock, AR 72206

AC Inspection - Rev. 2

Serial Number:

Location:

Description: 150HP 1780RPM WEG

Hi-Speed Job Number:	102593
Manufacturer:	WEG
Product Number:	15018EP3GBB445T
Spec/ID #:	ET
HP/kW:	150 (HP)
RPM:	1780 (RPM)
Frame:	444/5T
Voltage:	460
Current:	168 (Amps)
Phase:	Three
Hz:	60 (Hz)
Service Factor:	1.15
Enclosure:	TEFC
# of Leads:	12
J-box Included:	Complete
Coupling/Sheave:	None
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	No
Shaft Machined Fit Repairs Required:	Yes
Bearing Housing Machined Fit Repairs Required:	No
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: **a** 2 - High



10 - Good

Overall Condition

0

Report Date

P45







3. Photos of all six sides of the machine.













































4. Describe the Overall Condition of the Equipment as Received Serviceable

Initial Mechanical/Electrical

0

5. Does Shaft Turn Freely?

(Y) Yes

6. Does the shaft require T.I.R in Lathe to identify additional repairs?

(Yes) Yes


ODE bearing journal egg shaped



Some minor rust



8.	Assembled Shaft Runout	0.001 Inches	
9.	Assembled Shaft End Play	0 inches	
10.	Air Gap Variation <10%	pass	
11.	Lead Condition	(P) Pass	P69





12.	Lead Length	12 Inches
13.	Does it have Lugs?, If so what is the Stud Size?	(No) No

14. Lead Numbers P97

2,4,8,10 5,9,3,11 1,6,7,12



15. Frame Condition pass

▶ 16. Fan Condition (P) Pass P115



17. Broken or Missing Components

none

0

P8

Initial Electrical Inspection


. Insulation Resistance/Megger Megohms





19. Winding Resistance P20


1-2 1-3 2-3



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 3/8/2024 Powered by INSPECTALL Page 7 of 14







21.	Number of Stator Slots	72
22.	Stator Condition	pass
-	Wash and bake	

23. Stator Thermistors/Ohms



THERMISTOR/TERMISTOR (PTC)
Many, measuring undays 2.3 Volc
Many, feministry
1550

Pa

24. Stator Overloads/Ohms

Na

Mechanical Inspection

0

254.7

P90

25. Drive End Bearing Brand NSK

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 3/8/2024 Powered by INSPECTALL Page 8 of 14







27.	Drive End Bearing Qty.	1	
28.	Drive End Bearing Type	(Roller) Roller Bearing	
29.	Drive End Lubrication Type	(Grease) Grease Lubricated	
30.	Drive End Bearing Insulation or Grounding Device?	none	
31.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	snap ring	
32.	Drive End Bearing Condition	replace	P82





33.	Opposite Drive End Bearing Brand	SKF	
34.	Opposite Drive End Bearing Number-	6316 2Z/C3	P99



35.	Opposite Drive End Bearing Qty.	1	
36.	Opposite Drive End Bearing Type	(Ball) Ball Bearing	
37.	Opposite Drive End Lubrication Type	(Grease) Grease Lubricated	
38.	Opposite Drive End Bearing Insulation or Grounding Device?	none	
39.	Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	snap ring	
40.	Opposite Drive End Bearing Condition	replace	P118







41.	Drive End Seal	dust seal

42. Opposite Drive End Seal none

Rotor Inspection

43. Rotor Type/Material

(Squirrel Aluminum) Squirrel Cage Aluminum Die Cast

45. Number of Rotor Bars 46. Rotor Condition 47. Light the Barter residual for the Barreis Balance.	(Pass) Pass 58
47 Hattha Darta v. 1 17 d. D. 1 D.	pass
47. List the Parts needed for the Repair Below	
NU 319 roller bearing. 6316 2Z / C3 ball bearing	
48. Signature of Technician that Disassembled Motor	Terrence Holland
,	
Mechanical Fits- Rotor	
49. Shaft Runout	0.002 inches
50. Rotor Runout	Opposite Drive End Receips
Drive End Bearing Fit Rotor Body	Opposite Drive End Bearing
■ Na	
51. Coupling Fit Closest to Bearing Housing	
0 Degrees 90 Degrees	120 Degrees
3	J
Na	
52. Coupling Fit Closest to the end of the Shaft	
0 Degrees 60 Degrees	120 Degrees
■ Na	
53. Drive End Bearing Shaft Fit	400 D
0 Degrees 60 Degrees 3.7409 3.7407	120 Degrees 3.7409
 54. Drive End Bearing Shaft Fit Condition 	(P) Pass
55. Opposite Drive End Bearing Shaft Fit	(r) r ass
0 Degrees 60 Degrees	120 Degrees
3.15 3.1497	3.1443
Egg shaped.	
 56. Opposite Drive End Bearing Shaft Fit Condition 	(F) Fail
57. Shaft Air Seal Fits	
Drive End Air Seal Opposite Drive End A	Air Seal
good good	_
Mechanical Fits- Bearing Housings	0
58. Drive End - Endbell Bearing Fit	420 Dagge ==
0 Degrees 60 Degrees 7.474 7.4738	120 Degrees 7.4738
 59. Drive End - Endbell Bearing Fit Condition 	(P) Pass
60. Opposite Drive End - Endbell Bearing Fit	(1) 1 000
0 Degrees 60 Degrees	120 Degrees
6.6935 6.6932	6.6933
	(P) Pass

P52

Drive End Bearing Cap

Opposite Drive End Bearing Cap

pass









63. End Bell Air Seal Fits

Drive End Air Seal Opposite Drive End Air Seal

pass pass

64. List Machine Work Needed Below Repair ODE shaft bearing journal. It is egg shaped.

65. Technician Terrence Holland

Root Cause of Failure

0

66. Failure locations

Opposite drive end shaft bearing journal out of tolerance. Egg shaped. Bearing grease dirty/contaminated.









67. Root cause of failure

Both bearings had contaminated grease inside them and the ODE shaft bearing journal was out of allowable tolerance.

Dynamic Balance Report

68. Rotor Weight and Balance Grade

Rotor Weight Balance Grade

69. Initial Balance Readings

Drive End Opposite Drive End

70. Final Balance Readings

Drive End Opposite Drive End

71. Technician

Mechanical Fits- Rotor - Post Repair

- 72. Shaft Runout Post Repair
- 73. Rotor Runout Post Repair

Drive End Bearing Fit Rotor Body Opposite Drive End Bearing

74.	Coupling Fit Closest to Bearing F	lousing Post Repair		
	0 Degrees	90 Degrees	120 Degrees	
	0 D0g1000	00 Dog.000	120 20g.000	
75.	Coupling Fit Closest to the end o	f the Shaft Post Repair		
	0 Degrees	60 Degrees	120 Degrees	
	0 2 09.000	55 <u>-</u> 5 g . 555	:20 2 09:000	
76.	Drive End Bearing Shaft Fit Post	Repair		
	0 Degrees	60 Degrees	120 Degrees	
		- 1	1 19 111	
77.	Opposite Drive End Bearing Sha	ft Fit Post Repair		
	0 Degrees	60 Degrees	120 Degrees	
	ŭ	· ·	Ü	
78.	Shaft Air Seal Fits Post Repair			
	Drive End Air Seal	Opposite Drive End Air Seal		
79.	Shaft Repair Sign-off			
Assem	nbly			
80.	QC Check All Parts for Cleanline	ss Prior to Assembly		
81.	Photograph All Major Componen	ts prior to assembly		
82.	Final Insulation Resistance Test			
83.	Assembled Shaft Endplay			
84.	Assembled Shaft Runout			
85.	Test Run Voltage			
	Volts	Volts	Volts	
86.	Test Run Amperage			
	Amps	Amps	Amps	
87.	•			
	Horizontal	Vertical	Axial	
88.	Opposite Drive End Vibration Re	•		
	Horizontal	Vertical	Axial	
	A 1: (T			
89.	·			
90.	Drive End Bearing Temps - Fahr		4.5. Minutes	
	5 Minutes	10 Minutes	15 Minutes	
04	Opposite Drive Ford Bearing Town	no Cobronhoit		
91.	Opposite Drive End Bearing Tem		15 Minutos	
	5 Minutes	10 Minutes	15 Minutes	
00	Dogument Final Condition with D	inturna after point		
92. 93.	Document Final Condition with P Final Pics and QC Review	ictures arter paint		
93.	Filial Fics and QC Review			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.