



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

AC Inspection as Found
MIDDLETON INCORPORATED
P.O. BOX 506
BRYANT, AR 72089

FolderID: 103888
FormID: 22628784

AC Inspection - Rev. 2

Location: MOTOR SHOP LR
Serial Number: N2208270121-003
Description: HP 1.5

Hi-Speed Job Number:	103888
Product Number:	IE2-90S-2
Spec/ID #:	BARMESA
Serial Number:	0913021
HP/kW:	1.5 (HP)
RPM:	3485 (RPM)
Voltage:	230 / 460
Current:	5.52/2.76 (Amps)
Phase:	Three
Hz:	60 (Hz)
Enclosure:	TEFC
# of Leads:	9
J-box Included:	Complete
Coupling/Sheave:	None
Date Received:	12/17/2024
Bearing RTDs:	No
Stator RTDs:	No
Repair Stage:	Final
Rewind:	Yes
Shaft Machined Fit Repairs Required:	No
Bearing Housing Machined Fit Repairs Required:	No
Heaters:	No
Winding Type :	Random Wound
Bearing Type:	Rolling Element

Priorities Found: 1 - High 11 - Good

Overall Condition



1. Report Date

12/18/2024

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.


2. Nameplate Picture

P37



3. Photos of all six sides of the machine.

P45



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.







4. Describe the Overall Condition of the Equipment as Received
Wet but serviceable

Initial Mechanical/Electrical






5.	Does Shaft Turn Freely?	(Y) Yes
6.	Does the shaft require T.I.R in Lathe to identify additional repairs?	(No) No
7.	Does Shaft Have Visible Damage?	(No) No
8.	Assembled Shaft Runout	0.002 Inches
9.	Assembled Shaft End Play	0 inches
10.	Air Gap Variation <10%	
11.	Lead Condition	(P) Pass
12.	Lead Length	6 Inches

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

13.	Does it have Lugs?, If so what is the Stud Size?	(Yes) Yes	
14.	Lead Numbers	1-9	
15.	Frame Condition	pass	
16.	Fan Condition	(P) Pass	P115
			
17.	Broken or Missing Components	none	
Initial Electrical Inspection 			
18.	Insulation Resistance/Megger	Megohms	P8
			
19.	Winding Resistance		
	1-2	1-3	2-3
20.	Perform Surge Test	(F) Fail	P57
			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

21.	Number of Stator Slots	36	
22.	Stator Condition	rewind	
23.	Stator Thermistors/Ohms		
24.	Stator Overloads/Ohms		
Mechanical Inspection			
25.	Drive End Bearing Brand	NSK	P12
<div style="display: flex; justify-content: space-around;">   </div> <div style="display: flex; justify-content: space-around; margin-top: 20px;">  </div>			
26.	Drive End Bearing Number-	6305	
27.	Drive End Bearing Qty.	1	
28.	Drive End Bearing Type	(Ball) Ball Bearing	
29.	Drive End Lubrication Type	(Grease) Grease Lubricated	
30.	Drive End Bearing Insulation or Grounding Device?	none	
31.	Drive End Wavy Washer/Snap-Ring Other Retention Device?	snap ring	
32.	Drive End Bearing Condition	wet & rusted	
33.	Opposite Drive End Bearing Brand	NSK	P92

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



34. Opposite Drive End Bearing Number-	6205
35. Opposite Drive End Bearing Qty.	1
36. Opposite Drive End Bearing Type	(Ball) Ball Bearing
37. Opposite Drive End Lubrication Type	(Grease) Grease Lubricated
38. Opposite Drive End Bearing Insulation or Grounding Device?	none
39. Opposite Drive End Wavy Washer/Snap-Ring Other Retention Device?	wavy washer
40. Opposite Drive End Bearing Condition	wet & rusted
41. Drive End Seal	P120





Rotor Inspection



43. Rotor Type/Material

(Squirrel Aluminum) Squirrel
Cage Aluminum Die Cast

P3



44. Growler Test

(Pass) Pass

45. Number of Rotor Bars

20

46. Rotor Condition

good

47. List the Parts needed for the Repair Below

6205 & 6305 2Z/C3
Rewind stator

48. Signature of Technician that Disassembled Motor

Terrence Holland

Mechanical Fits- Rotor

49. Shaft Runout


0.002 inches

50. Rotor Runout


Drive End Bearing Fit


Rotor Body

Opposite Drive End Bearing

51.	Coupling Fit Closest to Bearing Housing		
	0 Degrees	90 Degrees	120 Degrees
52.	Coupling Fit Closest to the end of the Shaft		
	0 Degrees	60 Degrees	120 Degrees
53.	Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	0.9845	0.9846	0.9845
54.	Drive End Bearing Shaft Fit Condition		(P) Pass
55.	Opposite Drive End Bearing Shaft Fit		
	0 Degrees	60 Degrees	120 Degrees
	0.9845	0.9847	0.9844000000000001
56.	Opposite Drive End Bearing Shaft Fit Condition		(P) Pass
57.	Shaft Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
Mechanical Fits- Bearing Housings			
58.	Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	2.4413	2.4413	2.4415
59.	Drive End - Endbell Bearing Fit Condition		(P) Pass
60.	Opposite Drive End - Endbell Bearing Fit		
	0 Degrees	60 Degrees	120 Degrees
	1.5753	1.5752	1.575
61.	Opposite Drive End - Endbell Bearing Fit Condition		(P) Pass
62.	Bearing Cap Condition		
	Drive End Bearing Cap	Opposite Drive End Bearing Cap	
	pass	none	
63.	End Bell Air Seal Fits		
	Drive End Air Seal	Opposite Drive End Air Seal	
64.	List Machine Work Needed Below		
	None		
65.	Technician		Terrence Holland
			
	Co sign: DM		
Root Cause of Failure			
66.	Failure locations		
	Connection box.		
67.	Root cause of failure		
	Connection box seal gasket improperly installed allowing moisture to saturate the stator windings.		
Dynamic Balance Report			

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

68. Rotor Weight and Balance Grade		
Rotor Weight	Balance Grade	
69. Initial Balance Readings		
Drive End	Opposite Drive End	
70. Final Balance Readings		
Drive End	Opposite Drive End	
71. Technician		
Rewind		
72. Core Test Results - Watts loss per Pound		
Pre-Burnout	Post Burnout	
73. Core Hot Spot Test		
Pre-Burnout	Post-Burnout	
74. Post Rewind Electrical Test- Insulation Resistance		
75. Post Rewind Polarization Index		
76. Post Rewind Winding Resistance		
1-2	1-3	2-3
77. Post Rewind Surge Test		
78. Post Rewind Hi-Pot		
79. Technician		
Assembly		
80. QC Check All Parts for Cleanliness Prior to Assembly		Terrence Holland
		





83. Assembled Shaft Endplay **0 inches**

84. Assembled Shaft Runout **0.002 inches**

85. Test Run Voltage P56

Volts	Volts	Volts
459	457	459



86. Test Run Amperage

Amps	Amps	Amps
1.2	1.1	1.4

87. Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
------------	----------	-------

88. Opposite Drive End Vibration Readings - Inches Per Second

Horizontal	Vertical	Axial
------------	----------	-------

89. Ambient Temperature - Fahrenheit

90. Drive End Bearing Temps - Fahrenheit

5 Minutes	10 Minutes	15 Minutes
-----------	------------	------------


91. Opposite Drive End Bearing Temps - Fahrenheit


5 Minutes	10 Minutes	15 Minutes
-----------	------------	------------

92. Document Final Condition with Pictures after paint

P129

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.





93. Final Pics and QC Review

Terrence Holland

P131

[Handwritten signature]



