

LR Field Services

Prepared for Almatris Inc/RCP Bauxite (10014)

4701 Alcoa Road
Bauxite AR 72011

Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0
Field Service Ticket	3.0
Field Service Ticket	4.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

FolderID: 102806
FormID: 20143549

Job Information

- | | |
|------------------------|------------------------------|
| 1. Hi-Speed Job Number | 102806 |
| 2. Asset Type | Siemens air compressor motor |
| 3. Make | Siemens |
| 4. Model | |

*New motor first holes 10.25" second are 12.25. 14.25" wide
Old motor first holes 10.75" second are 13.75" 16" wide*




Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 05/16/2024

Powered by [INSPECTALL](#)

1.0



- 5. Serial Number
- 6. Customer Asset ID/Asset Name

Service Call Details

- 7. Service Objectives
Remove motor
- 8. Services Performed
Removed motor and looked at a motor base customer wants replaced.
- 9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

James Sherrill



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 102806
FormID: 20373684

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

Job Information

1. Hi-Speed Job Number	102806
2. Asset Type	Compressor motor
3. Make	Siemens
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	

Service Call Details

7. Service Objectives

Install motor and test run.

8. Services Performed

Installed motor. Wired up main leads and electrician wired up sensors. We used mica, high temp tape and rubberized tape on the leads. Insulated the box with live rubber for the leads.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Mark Henningsen



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 102806
FormID: 20384003

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

Job Information

- | | |
|---------------------------------|------------|
| 1. Hi-Speed Job Number | 102806 |
| 2. Asset Type | compressor |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

- | | |
|---------------------------------------|--|
| 7. Service Objectives | Watch motor do initial loaded start up. |
| 8. Services Performed | Process and power needs to order a part for the compressor so they are going to notify me when they get a game plan for me to be back. |
| 9. Service Technician Recommendations | |

Approval Signatures

- | | |
|----------------------------------|-------------|
| 10. Service Technician Signature | Trevor Hall |
|----------------------------------|-------------|

- | | |
|------------------------|-------------|
| 11. Customer Signature | David Wolfe |
|------------------------|-------------|



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 102806
FormID: 20404907

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

Job Information

1. Hi-Speed Job Number	102806
2. Asset Type	Compressor motor
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	

Service Call Details

7. Service Objectives

Witness startup of rebuilt motor.

8. Services Performed

We rechecked rotation, reinstalled the coupling. Started motor. Motor is very quiet and running smoothly. Amp gauge shows to be running at 100 amps loaded. Took vibration data. Process and power did the startup on the unit.



9. Service Technician Recommendations

Approval Signatures

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.


10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to read 'T. Hall', written in a cursive style.

11. Customer Signature

Mark Hennungen

A handwritten signature in black ink, appearing to read 'Mark Hennungen', written in a cursive style.