



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 102856
FormID: 20223423

Planters Cotton Oil Mill
2901 Planters Drive
Pine Bluff, AR 71601

Job Information

- | | |
|---------------------------------|--------|
| 1. Hi-Speed Job Number | 102856 |
| 2. Asset Type | |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details



7. Service Objectives
Field balance west side, east side, and strip fan

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



West side fan



West side fan



West side fan



East side fan



East side fan

East fan is rubbing the shroud,
it'll have to be done later

Small fan

Small fan could not get small
fan below 4 mils, suggest
checking bearings to see if
they are showing signs of wearWest side of East side fan has
all mounting hardware broken
off. Due to that I couldn't get it
under 5 mils

East side final

9. Service Technician Recommendations

Check inboard bearing on small fan and replace broken fasteners on all mounting points

Approval Signatures

10. Service Technician Signature

11. Customer Signature

Gabe Wood