



Field Service Ticket

FolderID: 103806
FormID: 22397355

Almatis Inc/RCP Bauxite (10014)
4701 Alcoa Road
Bauxite, AR 72011

Job Information



- | | |
|------------------------|-----------|
| 1. Hi-Speed Job Number | 103806 |
| 2. Asset Type | Ball mill |
| 3. Make | P3 |



- | | |
|---------------------------------|-----------------------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | Building 55 ball mill |

Service Call Details



- | |
|-------------------------------|
| 7. Service Objectives |
| Laser align motor to gearbox. |

8. Services Performed

Laser aligned motor gearbox as best as I could without having to move the gearbox. Motor is bolt bound and bolts have already been milled down as low as possible. Customer does not want to move the gearbox and said that they are fine with the final readings. Motor has an air clutch coupling with pads all the way around. Motor is 890 rpm. Beginning run was a new install and final readings were 0.3, -0.1 verticle and -0.3, -2.0 horizontal.



9. Service Technician Recommendations

Coupling on output of gearbox and pinion needs grease and a grease fitting.

Approval Signatures

10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to read "Trevor Hall".

11. Customer Signature

James Sherrill

A handwritten signature in black ink, appearing to read "James Sherrill".