



## Field Service Ticket

FolderID: 103916  
FormID: 22691172

Almatis Inc/RCP Bauxite (10014)  
4701 Alcoa Road  
Bauxite, AR 72011

### Job Information

- |                                 |                         |
|---------------------------------|-------------------------|
| 1. Hi-Speed Job Number          | 103916                  |
| 2. Asset Type                   | 6401 #12 dust collector |
| 3. Make                         |                         |
| 4. Model                        |                         |
| 5. Serial Number                |                         |
| 6. Customer Asset ID/Asset Name | #12dust collector       |

### Service Call Details

7. Service Objectives

*Balance fan*

8. Services Performed

*Add 30 gram to fan started at 4.1 and 1.3 and finish at 1.8 and .7 mils on fan end.. OB bearing needs to be tightened more and vibe should decrease.*


P8



Finish



Finish



Start

9. Service Technician Recommendations

*Check tightness of OB bearing*

### Approval Signatures

10. Service Technician Signature

Shon Jones

11. Customer Signature

Jeff Math Eweews

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.