

LR Field Services

Prepared for Rogers Group (01189502)

1032 Hwy 5
Cabot AR 72023

Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104718
FormID: 24697714

Rogers Group (01189502)

1032 Hwy 5
Cabot, AR 72023

Job Information

1. Hi-Speed Job Number	104718
2. Asset Type	250 hp motor and fan
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	ID fan


Service Call Details

7. Service Objectives

To remove motor, fan bearings and coupling. Reinstall new bearings and coupling, laser align motor to fan and then balance.

8. Services Performed

Same as objective



9. Service Technician Recommendations

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Approval Signatures


10. Service Technician Signature

Trevor Hall

A stylized, handwritten signature in black ink, appearing to be 'T. Hall'.

11. Customer Signature

Marcus Andrews

A handwritten signature in black ink, appearing to be 'Marcus Andrews'.



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104718
FormID: 24712366

Rogers Group (01189502)
1032 Hwy 5
Cabot, AR 72023

Job Information

- | | |
|------------------------|---|
| 1. Hi-Speed Job Number | 104718 |
| 2. Asset Type | 30 hp motor and gearbox on top of silos |
| 3. Make | |



- | | |
|---------------------------------|--|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

7. Service Objectives
To inspect 30 hp motor on gearbox.

8. Services Performed
We went up to scope out the job and then the main auger broke to their asphalt kiln so we then worked on the auger for most of the day, got it done and then we went back up to inspect the motor. The keyway was severely damaged so we installed a new motor and key, wired the motor up and test ran.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 06/06/2025

Powered by [INSPECTALL](#)

2.0



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Steven Carlton