

Job Information

Job #:	94474				Date:	July 26, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name: JA Riggs Motor#:

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	20
Serial#:	Z1106021736	Model#:	09E473T150G1	Service Factor:	1.15
Frame:	256TCZ	Rated RPM:	3525	Rated Voltage:	230/460
Phase:	3	Rated Amps:	46/23	Cycles:	60

Special design: No

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



10.6

AC Electrical Inspection

Megs at reassemb	oly: Good	Surge at reassemb	ly: Good	Hi-pot reassembly: Good		
Winding Resistance Incoming						
	Phases A to B	Phases B to C	Phases C to A	A Resistive imbalance		
Outgoing	0.365	0.369	0.363	0.9		
Test Run Inspection Date July 26, 2018						
Yes I have merged this motor and verified that all electrical tests are complete!						
Power Supply Phase A Phase B Phase C						
No Load Volta	ge	461	459	459		

10.8

Temperatures: (Degrees Fahrenheit)

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

10.5

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

No Load Current



MILLINGTON, TN LITTLE ROCK, AR

Test Run Inspection (Continued)

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak	(Readings should be less than .08 In/Sec Peak)			
	Horizontal	VDE	Axial	
DE	0.4	0.8	0.8	
ODE	0.5	0.4	0.6	

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos










Yes, the shaft has been isolated for delivery.

Service Tech name:

Terrence Holland

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301