

#### **Job Information**

Job #: 136599 Date: February 8, 2018

Priority: 3 Authorized OT: No Authorized by:

## **Customer Information**

Name: Usg Reason:

Contact: Will leadbetter Motor#: PO#:

Application: – Special notes:

#### **Name Plate Information**

Manufacturer: Reliance Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: P40g0240lbuvcj Model#: P40g0240n

Service Factor: 1.15 Frame: 405t

Horsepower/kW: 100 Rated RPM: 1785

Rated Amps: 112 Rated Voltage: 460

Phase: 3 Cycles:

No





Special design:











Fax 901-873-5301

CENTRAL ARKANSAS



# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Dirt

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device

present?: Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6316

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6316

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





## **Mechanical Inspection (Continued)**

Lubrication Type: Oil Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals ODE type:

Seals DE (inbound) condition :

Seals Image 2:

Seals ODE size:

Seals ODE (inbound) condition

Shaft damage cause: None

Slinger

Shaft Image:



Fax 901-873-5301



# **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket:

Ok



Fan:

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Other missing parts



## **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

N/a N/a DE @ 0 ODE @ 0

N/a DE @ 90 N/a **ODE @ 90** 

N/a N/a DE @ 180 ODE @ 180

N/a N/a DE @ 270 **ODE @ 270** 

## **AC Electrical Inspection**

Number of leads: 3 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads:

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads:

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition:

Connections As Received: Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment:



Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



#### **Rotor Test Results**

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







## **AC Electrical Inspection (Continued)**

Winding color: Like new

Winding image

Winding Thermal Protection:

Yes

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

If other, leads/jumpers:

Ok

Lead jumper Image.:



WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 fax 501-375-4254



#### **Conclusion**

**Component Failure** 

**Cause of Failure** 

Bearing

**Comments** 

Service Tech name: Scott Simon

Service Tech signature: