

Job Information

Job #: 137112 Date: April 18, 2018

Priority: — Authorized OT: No Authorized by: Terry f

Customer Information

Name: Insitufourm ms Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Siemens Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: Model#: Ile15031eb434aa

Service Factor: Frame: 180I

Horsepower/kW: 25 Rated RPM: 1775

Rated Amps: Rated Voltage: 460

Phase: 3 Cycles:

No

Nameplate DE ODE F1 F2 Top



Special design:











WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Dirt

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size:

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size:

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: N/A

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: 0 Grease Cond. DE: Hard

Grease Amt ODE: 0 Grease Cond. ODE: Hard

Seals DE type: Slinger Seals Image:

Seals DE size:

Not

Available

Seals DE (inbound) condition:

Seals Image 2:

Seals ODE type: Slinger

Seals ODE size:

Available

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket:

Ok

Fan: Ok

Frame cond.:

Good

Not Available Not Available



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads:

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads:

P2-Brown 2-White 6-No color assigned 3-Orange 7-No color assigned

4-Yellow 8-Red Lead condition:

Connections As Received:

Lug type:

Lug Condition: Terminal

Lug size:

Lug Attachment:



Lugs





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Imag







AC Electrical Inspection (Continued)

Winding color: Dull black Winding image Winding Thermal Protection: Yes

Winding condition: Mushy

Winding Thermal ____ Protection DE:

Winding Thermal _ Protection ODE:

Stator test results: Rewind

Not Available

Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

Not Stable Not Available



Conclusion

Component Failure

Ode rotor drag

Cause of Failure

Rewind quote new? Or rewind

Comments

Pole

Service Tech name: Terry f

Service Tech signature: