

Job Information

Job #: 137658 Date: August 20, 2018

Priority: 3 Authorized OT: No Authorized by:

Customer Information

Name: Mainline processing Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Serial#:

Manufacturer: Enclosure: Open Drop Proof Enclosure Type image

Model#:

(ODP)

Service Factor: Frame:

Horsepower/kW: Rated RPM:

Rated Amps: Rated Voltage:

Phase: Cycles:

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301

CENTRAL ARKANSAS



Mechanical Inspection

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE:

Worn

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Carbon

Shaft rotation: CW Contaminant(s) Amt: Full

Shaft grounding device No Contaminant Image:

present?:

Insulated: No Bearing DE Size:

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size:

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Bearings DE make:

FAG



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size:

Slinger

Seals Image 2:

Seals ODE size:

Seals ODE type:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: Other Shaft Image:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: Ok



Fan: Ok



Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 3 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads:

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads: P2-Brown

2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type:

Lug Condition: Terminal Lugs

Lug size:

Lug Attachment:





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Dull black Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal ___ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component Failure

Cause of Failure

Brake is bad

Comments

Service Tech name: Scott Simon

Service Tech signature:

State Since