

Job Information

Job #: 138004 Date: September 4,

2018

Priority: 3 Authorized OT: No Authorized by:

Customer Information

Name: Nucor Yamato Reason:

Contact: Rene daigle Motor#: PO#:

Application: – Special notes:

Name Plate Information

Serial#:

Manufacturer: Ge Enclosure: Open Drop Proof Enclosure Type image

(ODP)

P44g5210axw Model#: 5ke447bs223

Service Factor: 1.15 Frame: 447t

Horsepower/kW: 200 Rated RPM: 1780

Rated Amps: 222 Rated Voltage: 460

Phase: 3 Cycles:

Special design: No

Nameplate DE ODE F1 F2 Top













WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?: Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 6316

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6316

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image





Bearing Make Image

Bearing Retainer Image



Thermal Protection



Seals Image 2:



Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type: Slinger

Seals ODE size:

:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301

CENTRAL ARKANSAS



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: Ok



Fan: Ok



Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

N/a N/a DE @ 0 ODE @ 0

N/a DE @ 90 N/a **ODE @ 90**

N/a N/a DE @ 180 **ODE @ 180**

N/a N/a DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads:

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads:

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Bad

Connections As Received: Lug type:

Lug Condition: Warn Terminal

Lug size:

Lug Attachment: Acceptable









AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new

Winding image

Winding Thermal Protection:

Yes

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

If other, leads/jumpers:

Ok

Lead jumper Image.:



WEST TENNESSEE 7030 Ryburn Drive

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 fax 501-375-4254



Conclusion

Component Failure

Cause of Failure

Filled with water.

Comments

Service Tech name: Scott Simon

Service Tech signature:

LAA Q