

Job Information

Job #: 138781 Date: December 21,

2018

Priority: Authorized OT: No Authorized by:

Customer Information

Name: Consolidated Container Reason: Inspection

Contact: Jerry Shoemaker Motor#: PO#:

Application: Radial Load Special notes:

Name Plate Information

Manufacturer: **SEW** Enclosure: Open Drop Proof **Enclosure Type image**

(ODP)

D26DT100LS4 Serial#: Model#:

Service Factor: Frame:

Horsepower/kW: 3 Rated RPM: 1720

Rated Amps: 8.6/4.3 Rated Voltage: 230/460

Phase: 3 Cycles:

Yes

Nameplate DE ODE F1 F2 Top



Special design:













Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: NSK

Insulated: No Bearing DE Size: 6206

Bearings ODE: Worn Bearings ODE make: NSK

Bearing Type: Ball Bearing ODE Size: 6205

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE:

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE:

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: 0 Grease Cond. DE: New

Grease Amt ODE: Grease Cond. ODE: New

Seals DE type: Seals Image: Isolators

Seals DE size: See d.a report

Seals DE (inbound) condition: Worn

Seals ODE type:

Seals Image 2:

Seals ODE size: See d.a report

Seals ODE (inbound) condition Worn

Isolators

Shaft damage cause: Shaft Image: None



Fax 901-873-5301



Mechanical Inspection (Continued)





Bushings/sleeves image:



Water jacket:

N/A



Ok

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings: None

Length of leads: 12 inches REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 12-14 wag 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal

Lug size:

Lug Attachment: —

Terminal Lugs





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 28

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure: Stator good

Stator Image: Failure Image



Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color: Like new

Winding image

Winding Thermal Protection:

No

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Banet Wi



Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

If other, leads/jumpers:

Ok

Lead jumper Image.:





Conclusion

Component Fai	ilure
---------------	-------

Gear box failure

Cause of Failure

Wear and tear

Comments

Motor is good. Gear box needs work. Gear box is worn out. Needs fixed or replaced

Service Tech name: Dan Mahan

Service Tech signature:

D- h