

Job Information

Job #: 138799 Date:

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: KTG Reason:

Contact: Alex Motor#: 138799 PO#:

Application: Direct Drive Special notes:

Name Plate Information

Manufacturer: Siemens Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: Q2K13T0041NP1 Model#: SD100-IEEE

Service Factor: 1.15 Frame: 449TS

Horsepower/kW: 250 Rated RPM: 3575

Rated Amps: 265 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Yes Grease

> Shaft rotation: Bi-directional Contaminant(s) Amt: Quart

Shaft grounding device No

Contaminant Image: present?:

Shaft runout(TIR-Inbound): .001

Type of grounding device:

Bearings DE: Worn Bearings DE make: SKF

Insulated: Bearing DE Size: No 6318-zz

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Bearing ODE Size: Ball 6316-zz

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type:


Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: N/A

Lubrication brand inbound: Unknown Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: Full Grease Cond. DE: Watery

Grease Amt ODE: Full Grease Cond. ODE: Watery

Seals DE type: Seals Image: Other

Seals DE size: N/A

Seals DE (inbound) condition: Bad

Seals ODE type:

Seals Image 2:

Seals ODE size: N/A

Seals ODE (inbound) condition Bad

Other

Shaft damage cause: Shaft Image: None



Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A



Fan: Ok



Frame cond.: Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings: Two#2 Two#1 Two#3

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 12"

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: #4 P2-Brown

2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: Open Lug type: Reg

Lug size: #4

Lug Condition:

Lug Attachment: Acceptable

Good

Terminal









AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 58

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Other If other, stator type: Mush

Stator condition: Ok If other, stator condition: Good

Failure location: Other If other, stator failure: N/A

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.011765 0.011777 0.011797 0.3

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Com	ponent	Failure	

Bearings&clean up bad seals

Cause of Failure

Dirt

Comments

Service Tech name: Michael

Service Tech signature: