

### **Job Information**

Job #: 139116 Date: February 19,

2019

Priority: — Authorized OT: No Authorized by:

# **Customer Information**

Name: USB Reason: Motor inspection

Contact: Will Leadbetter Motor#: PO#:

Application: Direct Drive Special notes:

### **Name Plate Information**

Manufacturer: GE Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: Xj6436021 Model#: 5ks405ss208d11

Service Factor: Frame: 405T

Horsepower/kW: 100 Rated RPM: 1790

Rated Amps: 113 Rated Voltage: 460

Phase: 3 Cycles:

No

Nameplate DE ODE F1 F2 Top



Special design:











WEST TENNESSEE



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No

present?:

No

Contaminant Image:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6316zz

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6316zz

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





### **Mechanical Inspection (Continued)**

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: N/A Grease Cond. DE: Other

Grease Amt ODE: N/A Grease Cond. ODE: Other

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals DE (inbound) condition: Good

Seals Image 2:

Seals ODE size:

Seals ODE type:

N/A

Seals ODE (inbound) condition

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



## **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket:

N/A

Fan:

Ok

Frame cond.:

Good



an:



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None



Other missing parts



### **Mechanical Inspection (Continued)**

#### Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90** 

DE @ 180 **ODE @ 180** 

DE @ 270 **ODE @ 270** 

### **AC Electrical Inspection**

Number of leads: 3 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 16 inches

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 2 wag P2-Brown

2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type: None

Lug Condition: Terminal Lugs

Lug size:

Lug Attachment:

Fax 901-873-5301



## **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 60

Num broken bars: 0

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Coil head If other, stator failure:

Stator Image: Failure Image:







### **AC Electrical Inspection (Continued)**

Winding color: Dull black Winding image Winding Thermal Protection:

Winding condition: Solid

Winding Thermal \_\_\_ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind





Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





### **Conclusion**

**Component Failure** 

**Cause of Failure** 

Turn to turn short.

Comments

Windings blown in head.

Service Tech name: Dan Mahan

Service Tech signature:

