

Job Information

Job #:	139367				Date:	March 14, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Millington Memphis airport		Reason:	Motor inspection
Contact:	Mike gill	Motor#:		PO#:
Application:	Direct Drive	Special notes:		

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Open Drop Proof (ODP)	Enclosure Type image
Serial#:		Model#:	P56H3436R-YP	
Service Factor:		Frame:	56H	
Horsepower/kW:	1.5	Rated RPM:	1725	N.C.
Rated Amps:	5.6-5.6/2.8-3.0	Rated Voltage:	208-230/460-480	0
Phase:	3	Cycles:		
Special design:	No			

Nameplate

DE

ODE

F1

F2





Тор

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	NTN
Insulated:	No	Bearing DE Size:	6203zz
Bearings ODE:	Worn	Bearings ODE make:	NACHI
Bearing Type:	Ball	Bearing ODE Size:	6205zz
Bearings Retainer:	No	Thermal Protection:	No
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	N/A	Grease Cond. DE:	New
Grease Amt ODE:	N/A	Grease Cond. ODE:	New
Seals DE type:	N/A	Seals Image:	
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A	Seals Image 2:	
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N	/Α		Fan:	Ok	Frame cor	nd.: Good
			A VE			
Motor Mount Positio	n: Horizontal/Fo	oot mount			Endbell type:	Single piece
Missing parts?					Endbell Image:	
J-Box cover	O-rings	J-Box				
HH cover	Glands	V None				
Other missing parts	;					

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Mo	eaurements (N/A on Single Piece E	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	9	Terminal Markings:		
Length of leads:	6inches	REF: NEMA Stds Markings Identifi	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:	16 AWG	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Re	ceived:	
Lug Condition:	_	1	Terminal	Lugs
Lug size:				
Lug Attachment:	-			

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	g image	Winding Therma	I Protection:	No		
Winding condition :	Solid	-	Contraction of the second seco					
Winding Thermal Protection DE:								
Winding Thermal Protection ODE:	_							
Stator test results: Rewind								
Megs incoming: Goo	d	Surge incoming:	Good	Hi-pot in	coming:	Good		
Winding Resistance In	coming							
Phase	es A to B	Phases B to C	Phases	C to A	Resistive in	nbalance		
Incoming 12.3		12.4	12.2					
Leads/jumpe	ers: Ok		Lead jum	per Image. :				
If other, leads/jumpe	ers:							

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Brake

Cause of Failure

Comments

Motor is good. Brake makes rattling noise when power is induced to it. Brake needs to be replaced or rebuilt

Service Tech name:

Dan Mahan

Service Tech signature:

1 al

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301