

Job Information

Job #: 139376 Date: April 8, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: West Memphis utilities Reason: Motor inspection

Contact: Motor#: PO#:

Application: Direct Drive Special notes:

Name Plate Information

Manufacturer: Fairbanks Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: 232383 Model#:

Service Factor: Frame: 210t

Horsepower/kW: 14.6 Rated RPM: 1152

Rated Amps: 23.2 Rated Voltage: 460

Phase: 3 Cycles:

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6212 ZZ

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6207zz

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE:

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE:

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: 1/4 Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Seals Image: Other

Seals DE size: Mechanical

Seals DE (inbound) condition: Bad

Seals ODE type:

Seals Image 2:

Seals ODE size: Mechanical

Seals ODE (inbound) condition Ok

CENTRAL ARKANSAS

Other

Shaft damage cause: Shaft Image: None





Mechanical Inspection (Continued)





Bushings/sleeves image:



Water jacket:

N/A

Fan:

N/A

Frame cond.:

Good







Motor Mount Position:

Vertical Flange mount

Endbell type:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Endbell Image:



Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings:

Length of leads: 18 inches REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 12 awg 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: Good

Lug size:

Lug Attachment: —

Terminal



Lugs





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 38

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new

Winding image

Winding Thermal Protection:

No

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming:

Good

Surge incoming:

Bad

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

If other, leads/jumpers:

Ok

Lead jumper Image.:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 fax 501-375-4254



Conclusion

Component Failure

Seals and impeller

Cause of Failure

Customer dead headed Pump

Comments

Stator shorted.

Service Tech name: Dan Mahan

Service Tech signature:

D _ ___