

Job Information

Job #: 139627 Date: May 6, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Reason:

Contact: Motor#: 139627 PO#:

Application: Direct Drive Special notes:

Name Plate Information

Manufacturer: Magnaplus marathon Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: 743387-0318 Model#: 361CSL1600-1E

Service Factor: Continuous duty Frame: 361

Horsepower/kW: 40kw Rated RPM: 1800

Rated Amps: 139 Rated Voltage: 208

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top















Mechanical Inspection

Type of grounding device:

Shaft runout(TIR-Inbound):

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Oil

Shaft rotation: — Contaminant(s) Amt: Cup

Shaft grounding device yes Contaminant Image:

Stud

N/A

Bearings DE: Other Bearings DE make: Other

Insulated: No Bearing DE Size: N/A

Bearings ODE: Worn Bearings ODE make: NSK

Bearing Type: Ball Bearing ODE Size: 6310zz

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A Seals Image:

Seals DE size:

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type: N/A

Seals ODE size:

:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:





Fan:

Ok

Frame cond.: Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

✓ J-Box cover

O-rings

J-Box

☐ HH cover

Glands

☐ None

Other missing parts





Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 12 Terminal Markings: T1-t12

Length of leads: 18" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 6 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: 2Y Lug type: Reg

Lug Condition: Good Terminal Lugs

Lug size: 6

Lug Attachment: Acceptable





Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Other

Num rotor bars:

0

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Fail Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new

Winding image

Winding Thermal Protection:

No

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

Ok

Lead jumper Image.:



If other, leads/jumpers:



Conclusion

Component	Failure
-----------	----------------

Rewind fields and exciter on the rotor

Cause of Failure

Looks like something got into the wow,

Comments

Service Tech name: Michael Jordan

Service Tech signature: