

Job Information

139638 Job #: Date: April 29, 2019

Priority: Authorized OT: No Authorized by:

Customer Information

Name: **KTG** Reason: Motor inspection

PO#: Contact: Cindy Davis Motor#:

Application: Special notes:

Name Plate Information

Manufacturer: Us Enclosure: Open Drop Proof **Enclosure Type image**

(ODP) Serial#: Model#:

Service Factor: Frame: 405TS

3560 Horsepower/kW: Rated RPM:

Rated Amps: 224/112 Rated Voltage: 230/460

> Phase: 3 Cycles:

100

No

Nameplate DE ODE F1 F2 Top



Special design:













Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Yes None

> Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No

Contaminant Image: present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Other Bearings DE make: Koyo

Insulated: Bearing DE Size: 6316zz No

Bearings ODE: Other Bearings ODE make: Koyo

Bearing ODE Size: Bearing Type: Ball 6316zz

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type:

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Seals Image 2:



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A Seals Image:

Seals DE size:

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type: N/A

Seals ODE size:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301




Mechanical Inspection (Continued)





Bushings/sleeves image:



Water jacket: N/A



Fan: Ok



Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None



Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 18 inches

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 4 AWG P2-Brown

Terminal

2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: Standard Lug type:

Lug size: 4 AWG Lug Attachment:



Lugs

Lug Condition:

Good



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 52

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new

Winding image

Winding Thermal Protection:

No

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal

Protection ODE:

Stator test results: Salvageable



Megs incoming:

Good

Surge incoming:

Good

Hi-pot incoming:

Good

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

0.05

0.05

0.05

Leads/jumpers:

If other, leads/jumpers:

Ok

Lead jumper Image.:





Conclusion

Component Failure

Cause of Failure

Comments

Service Tech name: Dan Mahan

Service Tech signature:

