

Job Information

Job #: 139650 Date: April 30, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: MLGW Reason: Motor inspection

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Westinghouse Enclosure: Open Drop Proof Enclosure Type image

(ODP)
Serial#: 2 Model#: 17N6654

The contains a second contains

Service Factor: Frame: 505P

Horsepower/kW: 100 Rated RPM: 1175

Rated Amps: 118 Rated Voltage: 460

Phase: 3 Cycles:

No

Nameplate DE ODE F1 F2 Top



Special design:













present?:

Bearings DE:

Worn

Type of grounding device:

Shaft runout(TIR-Inbound):

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

Insulated: No Bearing DE Size: 7230

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: Mrc315szz

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image




Bearing Retainer Image

Bearings DE make:

SKF



Thermal Protection



Seals Image 2:



Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A Seals Image:

Seals DE size:

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type: N/A

Seals ODE size:

:

Shaft damage cause: None Shaft Image:

SA BARABA

Fax 901-873-5301

CENTRAL ARKANSAS



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:


N/A

Fan:

N/A

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

J-Box

☐ HH cover

Glands

☐ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 3 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 12 inches

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 2 AWG

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Worn

Connections As Received: Standard Lug type:

Lug Condition: Warn Terminal Lugs

Lug size: 2awg Lug Attachment:



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 90

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass


Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.071 0.071 0.071

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component Failure

Cause of Failure

Comments

Recommend reload and new lugs. Leads are worn as well as lugs.

Service Tech name: Dan Mahan

Service Tech signature:

D_ M_