

Job Information

Job #: 139659 Date: May 1, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Compressed air technologies Reason: Rewind

Contact: Bill perry Motor#: PO#:

Application: – Special notes: Rewind as a 60hz motor

Name Plate Information

Manufacturer: IR Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: 68194xg001 Model#: LS200L-T

Service Factor: Frame:

Horsepower/kW: 43 Rated RPM: 2965

Rated Amps: 77 Rated Voltage: 400

Phase: 3 Cycles: 50

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Other

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device

present?: Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: Other

Insulated: No Bearing DE Size: Nu312

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6214 ZZ

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Other Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: 1/4 Grease Cond. DE: New

Grease Amt ODE: 1/4 Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals DE (inbound) condition: Good

Seals Image 2:

Seals ODE size:

Seals ODE type:

N/A

Seals ODE (inbound) condition

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)





Bushings/sleeves image:



Water jacket: N/A



Fan: Ok



Frame cond.:



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

J-Box

☐ HH cover

Glands

☐ None

Other missing parts



Lugs



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

Length of leads: 4ft REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 2 AWG 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type: None

Lug Attachment: —

Terminal

Lug Condition:

Lug size:



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 40

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Other If other, stator condition:

Failure location: Coil head If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Dull black

Winding image

Winding Thermal Protection:

No

Winding condition:

Solid

Winding Thermal

Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming:

Bad

Surge incoming:

Bad

Hi-pot incoming:

Bad

Winding Resistance Incoming

Phases A to B

Phases B to C

Phases C to A

Resistive imbalance

Incoming

Leads/jumpers:

If other, leads/jumpers:

Ok

Lead jumper Image.:





Conclusion

Component Failure

Cause of Failure

Small screw in windings causing motor to blow

Comments

Service Tech name: Dan mahan

Service Tech signature:

