

Job Information

Job #: 139716 Date: May 10, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: University of Memphis Reason: Rewind

Contact: Jake hvac department Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Marathon Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: 00865950 Model#: 7n 445tstds4026cp

Service Factor: Frame: 445ts

Horsepower/kW: 200 Rated RPM: 1780

Rated Amps: 233 Rated Voltage: 460

Phase: 3 Cycles:

Special design: No

Nameplate DE ODE F1 F2 Top













WEST TENNESSEE

Contaminant Image:



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Dirt

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device

present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: NTN

Insulated: No Bearing DE Size: 6313zz

Bearings ODE: Worn Bearings ODE make: NTN

Bearing Type: Ball Bearing ODE Size: 6313zz

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Seals Image 2:



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: 1/4 Grease Cond. DE: Other

Grease Amt ODE: 1/4 Grease Cond. ODE: Other

Seals DE type: N/A Seals Image:

Seals DE size:

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type: N/A

Seals ODE size:

:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)





Bushings/sleeves image:



Water jacket:

N/A

Fan:

N/A

Frame cond.:

Good



-an:

Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

Length of leads: 18 inches REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 2 AWG 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Worn 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 42

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ground If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection:

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind





No

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.0573 0.0573 0.0573

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component Failure

Cause of Failure

Unknown

Comments

Stator is a rewind

Service Tech name: Dan Mahan

Service Tech signature:

D - m