

Job Information

Job #: 139732 Date: May 15, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Micro Port Orthopedics Reason:

Contact: Billy S Nunn Motor#: 139747 PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Lacertilia Enclosure: Totally Enclosed Enclosure Type image Fan Cooled

Serial#: IEC60034 Model#: AM100LBA2

Service Factor: 1.15 Frame: 100L

Horsepower/kW: 5.5 HP Rated RPM: 2835/3400

Rated Amps: 17.5/8.1 Rated Voltage: 208-230/460

Phase: 3 Cycles: 60

·

No

Nameplate DE ODE F1 F2 Top



Special design:











WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Other

Shaft rotation: — Contaminant(s) Amt: Other

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound): N/A

Type of grounding device:

Bearings DE: Worn Bearings DE make: Other

Insulated: No Bearing DE Size: 6206

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6206

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Good Thermal Protection Type: Thermocouple

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: Thermal Overloads

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Isolators Seals Image:

Seals DE size: 35x57x7

N/A

Seals DE (inbound) condition: Ok

Seals Image 2:

Seals ODE size:

Seals ODE type:

Seals ODE (inbound) condition

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)





Bushings/sleeves image:



Water jacket:

Ok



Fan:

Ok

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings: 1-6

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 8"

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 16

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Worn

Connections As Received: High Voltage Lug type: Reg

Lug Condition: Warn Terminal Lugs

Lug size: 16 Lug Attachment: Replace





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 28

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Fail Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type: Factory

Stator condition: Other If other, stator condition: Rewind

Failure location: In slot If other, stator failure: Inslot

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Dull black Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Component	Failure
-----------	---------

Bearings winding seals fans

Cause of Failure

Bad bearing

Comments

Service Tech name: Michael Jordan

Service Tech signature: