

Job Information

Job #: 139736 Date: May 22, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Cooper tire Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Harrington Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: Model#:

Service Factor: Frame:

Horsepower/kW: 1/2 ton Rated RPM:

Rated Amps: Rated Voltage:

Phase: Cycles:

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:

Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device

Other

present?: Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE:

Insulated: No Bearing DE Size:

Bearings ODE: Other Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size:

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image Bearing Make Image Bearing Retainer Image Thermal Protection



Bearings DE make:

FAG





Mechanical Inspection (Continued)

Lubrication Type: Oil Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals ODE type: Slinger

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:


Shaft damage cause: None

Seals Image 2:

Shaft Image:



Mechanical Inspection (Continued)



Bushings/sleeves image:



Water jacket:

Ok

Fan:

Ok

Frame cond.:

Good





Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Endbell Image:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

None



Other missing parts

Transformer and electromagnetic contactor



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: — Terminal Markings:

Length of leads:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

Connections As Received:

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned


Lead condition: — 4-Yellow 8-Red

Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —



Fax 901-873-5301

Failure Image:



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Rotor

Num rotor bars:

Num broken bars:

Rotor Test Results

Stator Image:

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal ___ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good


Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:





Conclusion

Com	poner	nt Fa	ilure
-----	-------	-------	-------

Cause of Failure

Missing parts

Comments

Service Tech name: Kev f

Service Tech signature: