

Job Information

Job #:	139761				Date:	May 20, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Desoto county regional utility		Reason:	Oil leak
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:		Enclosure :	Open Drop Proof (ODP)	Enclosu	ure Type image
Serial#:	11DW08581	Model#:	E8K-HD-E2W8X8		
Service Factor:		Frame:		A CARLER OF	
Horsepower/kW:		Rated RPM:	1300		
Rated Amps:		Rated Voltage:			A CALLER AND A
Phase:		Cycles:			
Special design:	No				
Nameplate	DE	ODE	F1	F2	Тор



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Other
Shaft rotation:	CW	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	HUA
Type of grounding device:			
Shaft runout(TIR-Inbound):	.002		
Bearings DE:	Worn	Bearings DE make:	FAG

Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	NJ210-E-XL-TVP2-C3
Bearings ODE:	Worn	Bearings ODE make:	Коуо
Bearing Type:	Ball	Bearing ODE Size:	7210 58C3
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	-	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

_	Thermal Protection device DE:	Oil	Lubrication Type:
_	Thermal Protection device ODE:	Mobile Polyrex EM	Lubrication brand inbound:
		Mobile Polyrex EM	Lubrication brand outbound:
New	Grease Cond. DE:	Full	Grease Amt DE:
New	Grease Cond. ODE:	Full	Grease Amt ODE:
	Seals Image:	Other	Seals DE type:
A Maria			Seals DE size:
		Worn	Seals DE (inbound) condition :
	Seals Image 2:		
		Other	Seals ODE type:
			Seals ODE size:
		Worn	Seals ODE (inbound) condition
	Shaft Image:	Other	Shaft damage cause:



WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301




Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:





WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	_	Terminal Markings:		
Length of leads:		REF: NEMA Stds Markings Identifie	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	_	4-Yellow	8-Red	
Lug type:		Connections As Red	ceived:	
Lug Condition:	-	r	erminal	Lugs
Lug size:				-
Lug Attachment:	_	AV	NOT	NOT AVAILABLE

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type:	Cast Aluminum				Rotor
Rotor Condition:	Ok	Num rotor bars: Num broken bars:			
Rotor Test Results Visual: Pass		Growler:	Pass	Single phase:	Pass
Stator type:	Factory		If other, stator ty	vpe:	
Stator condition:	Ok		If other, stator condit	ion:	
Failure location:	In slot		If other, stator fail	ure:	
Stator Image:			Failure Ima	age:	

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color: Like new		Winding im	age Winding	Thermal Protection:	Yes
Winding condition :	Solid				
Winding Thermal Protection DE:	_				
Winding Thermal Protection ODE:	_				
Stator test results:	Rewind				
Megs incoming: Goo	d	Surge incoming: G	ood	Hi-pot incoming:	Good
Winding Resistance In	coming				
Phase	es A to B	Phases B to C	Phases C to A	Resistive im	balance
Incoming					
Leads/jumpe	ers: Ok		Lead jumper Imag	ge.:	
If other, leads/jumpe	ers:				

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Seals and seal fits

Cause of Failure

Wear

Comments

Service Tech name: Kev f

Service Tech signature:

'Lev

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301